



Firmware Version: V1.70.012
Prom Code Version: V1.00.016
Published: 2020/02/26

These release notes include important information about D-Link DGS-1510 Series firmware revisions. Please verify that these release notes are correct for your switch:

- If you are installing a new switch, please check the hardware version on the device label; make sure that your switch meets the system requirement of this firmware version. Please refer to [Revision History and System Requirement](#) for detailed firmware and hardware matrix.
- If the switch is powered on, you can check the hardware version by typing "show version" command or by checking the device information page on the web graphic user interface.
- If you plan to upgrade to the new firmware release, please refer to the [Upgrade Instructions](#):

D-Link switches support firmware upgrade via TFTP server. You can download the firmware from D-Link web site <http://tsd.dlink.com.tw>, and copy the downloaded firmware to the TFTP server folder. Please make sure that the TFTP server is accessible from the switch via networks.

For more detailed information regarding DGS-1510 Series switch products, please refer to [Related Documentation](#).

You can also download the switch firmware, D-View modules and technical documentation from <http://tsd.dlink.com.tw>.

Content:

Revision History and System Requirement.....	3
Upgrade Instructions:	3
Upgrade using CLI (RJ-45 console port)	3
Upgrading by using Web-UI	4
New Features	7
Changes of MIB & D-View Module.....	8
Changes of Command Line Interface	8
Problem Fixed.....	9
Known Issues	11
Related Documentation	11

Revision History and System Requirement

Firmware Version	Date	Model	Hardware Version
Runtime: v1.70.012 PROM: v1.00.016	2020/02/26	DGS-1510	A1/A2/A3
Runtime: v1.60.012 PROM: v1.00.016	2018/11/5	DGS-1510	A1/A2
Runtime: v1.50.021 PROM: v1.00.015 (due to new models addition, DGS-1510-52XMP A1 & DGS-1510-52X A2, no impact to existing models)	2018/01/12	DGS-1510	A1/A2
Runtime: v1.40.019 PROM: v1.00.012	2017/09/10	DGS-1510	A1
Runtime: v1.30.007 PROM: v1.00.012	2015/10/20	DGS-1510	A1
Runtime: v1.20.011 PROM: v1.00.012	2015/5/2	DGS-1510	A1
Runtime: v1.10.005 PROM: v1.00.011	2014/5/21	DGS-1510	A1
Runtime: v1.00.031 PROM: v1.00.009	2014/1/15	DGS-1510	A1
Runtime: v1.00.029 PROM: v1.00.009	2014/1/13	DGS-1510	A1

Upgrade Instructions:

D-Link switches support firmware upgrade via TFTP server. You can download the firmware from D-Link web site <http://tsd.dlink.com.tw>, and copy the downloaded firmware to the TFTP server folder. Please make sure that the TFTP server is accessible from the switch via networks.

Upgrade using CLI (RJ-45 console port)

Connect a workstation to the switch console port and run any terminal program that can emulate a VT-100 terminal. The switch console port default settings are as follows:

- ◆ Baud rate: **115200**
- ◆ Data bits: **8**
- ◆ Parity: **None**
- ◆ Stop bits: **1**

The switch will prompt the user to enter his/her username and password. The default username and password are as below:

Username: **admin**

Password: **admin**

To upgrade the switch firmware, execute the following commands:

Command	Function
copy tftp://location/filename flash: filename	Download firmware file from the TFTP server to the switch.
boot image URL(filename)	Change the boot up image file.
show boot	Display the information of current boot image and configuration.
reboot	Reboot the switch.

Example:

DGS-1510#copy tftp: //192.168.0.27/firmware.had flash: run.had

```
Address of remote host [192.168.0.27]
Source filename [firmware.had]
Destination filename [run.had]
Accessing tftp://192.168.0.27/ firmware.had...
Transmission start...
Transmission finished, file length 5156864 bytes.
Please wait, programming flash... Done
```

DGS-1510#configure terminal
DGS-1510(config)#boot image c:/switch-image1.had

DGS-1510#show boot

```
Unit 1
Boot image: /c:/1.20.B014
Boot config: /c:/config.cfg
```

DGS-1510#reboot
Are you sure you want to proceed with the system reboot? (y|n) y
Please wait, the switch is rebooting...

Upgrading by using Web-UI

1. Connect a workstation installed with java SE runtime environment to management port of the device and also connect console cable to switch’s console port.
2. Open the web browser from the workstation and enter the IP address of the switch. The switch’s default IP address is **10.90.90.90**
3. Enter administrator’s username and password when prompted. **It should be noted starting from R1.20 formal firmware release the default login settings are as below:**

Username: admin


Password: admin

4. To update switch's firmware or configuration file via TFTP, select **Tools > Firmware Upgrade**


& Backup > Firmware Upgrade from TFTP.




5. Enter the TFTP Server IP address.
6. Enter the name of the firmware file located on the TFTP server.
7. Enter the destination path and the desired file name.
8. Click "**Upgrade**" button.




9. Transmission will start and wait until the status is completed by displaying **100%** complete.
10. Alternatively, the switch's firmware or configuration file can also be upgraded via HTTP, select **Tools > Firmware Upgrade & Backup > Firmware Upgrade from HTTP.**



11. Enter the source and destination file.
12. Click "**Upgrade**" button.



13. Transmission will start and wait until the status is completed by displaying **100%** complete.
14. To select the boot up image used for next reboot, click **Management > Flash System** in the function tree and then click the **C:** drive name. When you see the files list, click corresponding **Boot Up** button to specify the firmware that will be used for next and subsequent boot up.





15. To reboot the switch, select **Tools > Reboot System** from the banner.



16. Select **Yes** and click **Reboot** button to reboot the switch.



New Features

Firmware Version	New Features
V1.70.012	<ol style="list-style-type: none"> VLAN Wizard (Web UI only) "Do" command to support "Do show" option with "?" & <Tab>" (CLI only) DHCP Server "Show interfaces gbic" command (CLI only)
V1.60.012	<ol style="list-style-type: none"> Changing output's format when executing show running config command Removing Java from web page Set one boot image on stacked units Display slave's information of stacked unit via "show tech-support" command IGMP V3 protocol

	<ol style="list-style-type: none"> 6. "Do" command in EXEC mode 7. Configure Secondary IP setting via IPv4 interface in Web UI
V1.50.021	<ol style="list-style-type: none"> 1. Login Banner 2. Exec Banner 3. Supports Monitor logging in CLI 4. Session timeout (for outgoing remote session) 5. "show interface xx description" command in CLI 6. Add logging feature for ARP Spoofing Prevention 7. Enhance static multicast mac address table from 128 to 256 8. Supports SHA-256 for SSH 9. Enhance RADIUS Accounting for Command Logging (for TACACS+ accounting ONLY)
V1.40.019	<ol style="list-style-type: none"> 1. Add UDP helper 2. Enhance the show logging output for stacking features 3. Enhance priority between IP Source Guard and user-defined ACL 4. Change IPv6 Route Advertisement from host to router mode 5. Add LBD v4.07 6. Add Auto Surveillance VLAN 2.0 7. Add stacking MIBs for G2 CLI, swUnitMgmtStartPort,swUnitMgmtPortRange 8. Add TLS 1.2 9. Enhance CLI for "Show running-config" with output modifiers [effective all] [interface INTERFACE-ID] 10. Enhanced login page for Web UI to have the "username : admin" being filled in 11. Enhance Trap Source Interface in "SNMP Global Setting" page 12. Add PD-Alive
V1.30.007	<ol style="list-style-type: none"> 1. Add a New encryption method based on MD5 2. MAC-based VLAN 3. Protocol-based VLAN 4. Telnet Client (w/o MIB/Web) 5. SSH & telnet session timeout behavior change 6. Displaying web UI sessions in "show users" command 7. VLAN Cloning in web UI 8. Auto saving of configuration made from DDP protocol 9. Update a new web UI top image
V1.20.011	<ol style="list-style-type: none"> 1. Add NTP (RFC5905) 2. Modify IP interface from 8 to 16 3. Modify STP edge default settings to "True" 4. Add ERPS 5. Add sFlow 6. Add default username (admin) & password (admin)
V1.10.005	<ol style="list-style-type: none"> 1. Existing 4 models can now Physical Stack with 2 new members (DGS-1510-28X & DGS-1510-52X) 2. Add BPDU Attack Protection 3. Add the Command "Trace route" 4. Add the Command "prompt" for customizing CLI prompt 5. Add "Login Method" page for Web UI (for telnet session setup requirements under Web UI) 6. Supports D-Link's new IP Cameras' MAC Address ranges: B0:C5:54:00:00:00 ~ B0:C5:54:7F:FF:FF for Auto Surveillance VLAN 7. Modify user-defined OUI of Auto Surveillance VLAN & Auto Voice VLAN from 5 to 10 8. Modify web-UI's smart wizard to include a last step for configuring username & password
V1.00.031	None

V1.00.029 | First release, please refer to datasheet and manual for detail function support

Changes of MIB & D-View Module

The new features of MIB file are also included in the corresponding D-View module. Please download the D-View module on <http://tsd.dlink.com.tw>. For detailed changes of MIB content, please refer to the modification history in each MIB file.

Firmware Version	MIB File
V1.70.012	Update the following MIBs: 1. DLINKSW-DHCP6-SERVER-MIB.mib
V1.60.012	Update the following MIBs: 1. DLINKSW-IPMCAST-EXT-MIB.mib 2. DLINKSW-NETWORK-PROTOCOL-PORT-PROTECT.mib
V1.50.021	Update the following MIBs: 1. DLINKSW-SYSLOG-MIB.mib 2. DLINKSW-ASP-MIB.mib 3. DLINKSW-SURVEILLANCE-VLAN-MIB 4. SWDGS1510PRIMGMT-MIB
V1.40.019	Modify the below MIBs: 1. DLINKSW-STACK-MIB.mib 2. DLINKSW-SSL-MIB.mib 3. DLINKSW-IP-EXT-MIB.mib 4. DLINKSW-ACL-MIB.mib 5. IP-MIB.mib 6. DLINKSW-SURVEILLANCE-VLAN-MIB.mib 7. DLINKSW-POE-MIB.mib
V1.30.007	1. Add new feature UDP helper in D-View 2. Add new feature MAC Based VLAN in D-View 3. Add new feature Protocol Based VLAN in D-View
V1.20.011	1. Add DLINKSW-SFLOW-MIB 2. Add DLINKSW-ERPS-MIB 3. Add DLINKSW-NTP-MIB
V1.10.005	1. Add DLINKSW-BPDU-PROTECTION-MIB.mib 2. Add DISMAN-TRACEROUTE-MIB.mib 3. Modify DGS-1510 Series Physical Stacking for 6 models in D-View (2 new models DGS-1510-28X, DGS-1510-52X) 4. Add new features BPDU Protection in D-View 5. Add new features Trace Route in D-View
V1.00.031	None
V1.00.029	First release, please refer to datasheet for detail MIB support

Changes of Command Line Interface

The section below only shows command line changes that may bring backward compatibility issues with configuration settings for previous version of firmware. Any new feature commands that do not have backward compatibility issues are not included in the below section.

Firmware Version	Changes
V1.70.012	<p>1. Do command do show command</p> <p>2. TLS crypto pki certificate generate</p> <p>3. Show interfaces gbic show interfaces gbic</p> <p>4. CoA aaa server radius dynamic-author no aaa server radius dynamic-author authentication command bounce-port ignore no authentication command bounce-port ignore authentication command disable-port ignore no authentication command disable-port ignore</p> <p>5. DHCP option 82 ip dhcp relay information option format remote-id {default string STRING vendor2 vendor3 expert-udf [standalone_unit_format {0 1}]} ip dhcp relay information option format circuit-id { default string STRING vendor1 vendor2 vendor3 vendor4 vendor5 vendor6 expert-udf [standalone_unit_format {0 1}]} ip dhcp relay information option format-type remote-id { vendor3 string STRING expert-udf NAME } ip dhcp relay information option format-type circuit-id { vendor3 string STRING expert-udf NAME } ip dhcp relay information option mac-format case {lowercase uppercase} delimiter{hyphen colon dot none } number {1 2 5}</p> <p>6. DHCP Server address range START-IP-ADDRESS END-IP-ADDRESS no address range START-IP-ADDRESS END-IP-ADDRESS boofile URL no bootfile clear ip dhcp {all pool NAME } binding {* IP-ADDRESS} clear ip dhcp {all pool NAME } conflict {* IP-ADDRESS} clear ip dhcp server statistics class NAME no class NAME client-identifier IDENTIFIER no client-identifier default-router IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8] no default-router IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8] domain-name NAME no domain-name dns-server IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8]</p>

```

no dns-server IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8]
hardware-address HARDWARE-ADDRESS
no hardware-address
host {IP-ADDRESS MASK | IP-ADDRESS/PREFIX-LENGTH}
no host
ip dhcp class NAME
no ip dhcp class NAME
ip dhcp excluded-address START-IP-ADDRESS END-IP-ADDRESS
no ip dhcp excluded-address START-IP-ADDRESS END-IP-ADDRESS
ip dhcp ping packets COUNT
no ip dhcp ping packets
ip dhcp ping timeout MILLI-SECONDS
no ip dhcp ping timeout
ip dhcp pool NAME
no ip dhcp pool NAME
ip dhcp use class
no ip dhcp use class
lease { DAYS [HOURS [ MINUTES]] | infinite }
no lease
netbios-node-type NTYPE
no netbios-node-type
netbios-name-server IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8]
no netbios-name-server IP-ADDRESS [IP-ADDRESS2 ... IP-ADDRESS8]
next-server IP-ADDRESS
no next-server
network {NETWORK-ADDRESS MASK | NETWORK-ADDRESS /PREFIX-LENGTH }
no network
option CODE hex PATTERN [*] [bitmask MASK]
no option CODE hex PATTERN [*] [bitmask MASK]
service dhcp
no service dhcp
show ip dhcp binding [IP-ADDRESS]
show ip dhcp conflict [ IP-ADDRESS]
show ip dhcp pool [NAME]
show ip dhcp server
show ip dhcp server statistics

```

7. DHCPv6 Server

```

address prefix IPV6-PREFIX/PREFIX-LENGTH [ lifetime VALID-LIFETIME
PREFERRED-LIFETIME ]
no address prefix
address-assignment IPV6-ADDRESS CLIENT-DUID [ iaid IAID ] [ lifetime
VALID-LIFETIME PREFERRED-LIFETIME ]
no address-assignment IPV6-ADDRESS CLIENT-DUID [ iaid IAID ]
clear ipv6 dhcp binding { all | IPV6-ADDRESS}
domain-name DOMAIN-NAME
no domain-name
dns-server IPV6-ADDRESS
no dns-server IPV6-ADDRESS
ipv6 dhcp excluded-address LOW-ADDRESS [ HIGH-ADDRESS ]
no ipv6 dhcp excluded-address LOW-ADDRESS [ HIGH-ADDRESS ]
ipv6 dhcp pool POOL-NAME
no ipv6 dhcp pool POOL-NAME
ipv6 dhcp server POOL-NAME [rapid-commit] [preference VALUE ] [allow-hint]
no ipv6 dhcp server
ipv6 local pool POOL-NAME IPV6-PREFIX / PREFIX-LENGTH ASSIGNED-LENGTH

```

	<pre>no ipv6 local pool POOL-NAME prefix-delegation IPV6-PREFIX / PREFIX-LENGTH CLIENT-DUID [iaid IAID] [lifetime VALID-LIFETIME PREFERRED-LIFETIME] no prefix-delegation IPV6-PREFIX / PREFIX-LENGTH prefix-delegation pool POOL-NAME [lifetime VALID-LIFETIME PREFERRED-LIFETIME] no prefix-delegation pool POOL-NAME service ipv6 dhcp no service ipv6 dhcp show ipv6 dhcp [interface [INTERFACE-ID]] show ipv6 dhcp binding [IPV6-ADDRESS] show ipv6 dhcp pool [POOL-NAME] show ipv6 excluded-address show ipv6 local pool [POOL-NAME] show ipv6 dhcp operation</pre>
V1.60.012	<p>1. Network Protocol Port Protect network-protocol-port protect {tcp udp} no network-protocol-port protect {tcp udp} show network-protocol-port protect</p> <p>2. IP Multicasting ip multicast table-lookup-mode { ip mac} no ip multicast table-lookup-mode show ip multicast</p> <p>3. Boot image command boot image [check] [all] URL</p> <p>4. Tech Support command show tech-support [unit UNIT-ID] debug show tech-support [unit UNIT-ID]</p> <p>5. Do Command do COMMAND</p>
V1.50.021	<p>1. "show interface xx description" command in CLI: show interfaces [INTERFACE-ID [, -]] description</p>
V1.40.019	<p>1. LBD loopback-detection address-type { multicast broadcast } no loopback-detection address-type</p> <p>2. Surveillance VLAN surveillance vlan onvif-discover-port <value 554, 1025-65535> no surveillance vlan onvif-discover-port surveillance vlan onvif-ipc IP-ADDRESS state {enable disable} no surveillance vlan onvif-ipc IP-ADDRESS state surveillance vlan onvif-ipc IP-ADDRESS description TEXT no surveillance vlan onvif-ipc IP-ADDRESS description surveillance vlan onvif-nvr IP-ADDRESS description TEXT no surveillance vlan onvif-nvr IP-ADDRESS description show surveillance vlan onvif-ipc interface [INTERFACE-ID [, -]] {brief detail } show surveillance vlan onvif-nvr interface [INTERFACE-ID [, -]] [ipc-list]</p> <p>3. UDP helper ip helper-address IP-ADDRESS no ip helper-address [IP-ADDRESS]</p>

```
ip forward-protocol udp [PORT]
no ip forward-protocol udp [PORT]
show ip helper-address [INTERFACE-ID]
show ip forward-protocol udp
```

4. ACL

Add "vlan-range MIN-VID MAX-VID" option

5. TSL 1.2

```
ssl-service-policy POLICY-NAME
[version [ssl3.0] [tls1.0] [tls1.1] [tls1.2] ] |
[ ciphersuite
[dhe-dss-3des-edc-cbc-sha]
[rsa-3des-edc-cbc-sha]
[rsa-rc4-128-sha]
[rsa-rc4-128-md5]
[rsa-export-rc4-40-md5]
[rsa-aes-128-cbc-sha]
[rsa-aes-256-cbc-sha]
[rsa-aes-128-cbc-sha256]
[rsa-aes-256-cbc-sha256]
[dhe-dss-aes-256-cbc-sha]
[dhe-rsa-aes-256-cbc-sha] ] |
secure-trustpoint TRUSTPOINT |
session-cache-timeout TIME-OUT ]
```

```
no ssl-service-policy POLICY-NAME
[version [ssl3.0] [tls1.0] [tls1.1] [tls1.2] ] |
[ ciphersuite
[dhe-dss-3des-edc-cbc-sha]
[rsa-3des-edc-cbc-sha]
[rsa-rc4-128-sha]
[rsa-rc4-128-md5]
[rsa-export-rc4-40-md5]
[rsa-aes-128-cbc-sha]
[rsa-aes-256-cbc-sha]
[rsa-aes-128-cbc-sha256]
[rsa-aes-256-cbc-sha256]
[dhe-dss-aes-256-cbc-sha]
[dhe-rsa-aes-256-cbc-sha] ] |
```

6. SNMP

```
no snmp-server host { <IP-ADDRESS> | <IPV6-ADDRESS> }
[ <community-name> ]
```

V1.30.007

New encryption method based on MD5

1. username NAME [privilege LEVEL] [nopassword | password [0 | 7 | 15] PASSWORD]
2. enable password [level PRIVILEGE-LEVEL] [0| 7 | 15] PASSWORD
3. service password-encryption [7 | 15]

Telnet Client (w/o MIB/Web)

1. telnet [IP-ADDRESS | IPV6-ADDRESS | Domain Name] [TCP-PORT]

Displaying web UI sessions in "show users" command

1. clear line LINE-ID

V1.20.011	None
V1.10.005	None
V1.00.031	None
V1.00.029	First release

Problem Fixed

Firmware Version	Problems
V1.70.012	<ol style="list-style-type: none"> Fixed PoE's power utilization ratio in relation to total PoE budget in a given switch (DUSA20181018000003-Canada) Fixed multicast filtering-mode bug of not saving the configuration when executing a change (DUSA20181109000001-USA) Fixed "Reset System" bug under webUI environment (DRU20181128000004-Russia) Fixed SSH RSA's bug when host key generated was not initialized after a reboot (DRU20181128000002-Russia) Fixed an issue when deleting an admin account with a pop-up warning message (DRU20181128000003-Russia) Fixed "show tech-support" bugs when the switch resources are hogged by physical stacking and not able to process STP packets (DI20190118000001, DI20190401000002-Japan) Fixed "show tech-support" bug where its output is incomplete and providing wrong information (DI20190118000004-Japan) Fixed default IP address bug when it was not successfully removed after being saved and rebooted (DI20190129000002-Japan) Fixed Physical Stacking & User Authentication bugs when a new stack master was elected and the admin is not able to SSH into it (DI20190122000003, DI20190122000004, DI20190221000001-Japan) Fixed a bug where switch is sending a wrong OID (DI20190118000006-Japan) Fixed MAC based Access Control bug when its database is out of sync and caused its operation to fail (DI20190214000004-Japan) Fixed DHCP Snooping bug when modifying VLAN settings (DRU20190221000002-Russia) Fixed Physical Stacking missing stacking member bug

- (DRU20190221000002-Russia)
14. Fixed DHCP Snooping binding bug of displaying wrong VLAN ID
(DRU20190219000003-Russia)
 15. Fixed Recurring date daylight savings setting bug in WebUI
(DI20190304000001-Australia)
 16. Fixed default admin account's configuration modification bug of not taking effect after a reboot (DEUR20190226000006-Europe)
 17. Fixed VLAN interface bug where it is displaying wrong configuration in WebUI's edit page (DEUR20190329000004-Europe)
 18. Fixed NTP bug in Slave switches under Physical Stacking environment
(DEUR20190329000004-Europe)
 19. Fixed 802.1X bug when working with 2 Radius Servers
(DRU20190619000002-Russia)
 20. Fixed DHCP Snooping's bug when Voice VLAN is enabled & bug in Physical Stacking where slave switches firmware upgrade process timeout
(DRU20190401000007-Russia)
 21. Fixed Voice VLAN bug when working with Avaya IP phone
(DRU20190401000006)
 22. Fixed 10G port bug when forcing it to 1 Gigabit speed mode
(DEUR20181211000001-Europe)
 23. Fixed Radius Accounting's Session ID bug (DLA20190425000004-DLA)
 24. Fixed Admin account's bug where it is still present after being deleted. This happened when a switch config is restored via cfg file process
(DRU20190911000005-Russia)
 25. Fixed Radius Source Interface bug of not applying the correct IP address of the Network Access Server (DLA20190925000001-DLA)
 26. Fixed DHCP Snooping process bug of always hogging CPU resources
(DI20190312000001-Japan)
 27. Fixed 'show tech-support' process bug by enlarging & enhancing its memory utilization (DI20190307000003-Japan)
 28. Fixed 'show tech-support' bug of not able to display slave switches [under Physical Stacking] information via telnet/SSH (DI20190315000001-Japan)
 29. Fixed RADIUS Attribute's bug of applying the wrong Service-type
(DI20190325000004-Japan)
 30. Fixed IPv6 MLD Snooping's static group bug of not being saved

	<p>(DI20190903000007-Japan)</p> <p>31. Fixed & enhanced the process of running the command "debug copy tech-support tftp: " via tftp server (DI20190605000001-Japan)</p>
V1.60.012	<ol style="list-style-type: none"> 1. Fixed http secure server bug of not synchronizing properly (DI20171204000001-Japan) 2. Fixed Secondary IP interface is not being shown when configured (DI20180418000003, DI20171129000004-Japan) 3. Fixed memory overflow bug on ARP aging-time feature (DI20171130000004-Japan) 4. Fixed STP & LBD bug, which is able to enable in the same port (DI20171218000002, DI20180418000006-Japan) 5. Fixed SNTP syntax error in Web UI (DI20180222000004, DI20180418000004-Japan) 6. Fixed CLI charset default to ASCII (DI20180213000003, DI20180418000005-Japan) 7. Fixed UDP BLAT attack function missing from DoS feature (DI20180223000004, DI20180419000001-Japan) 8. Fixed Web UI syntax error under Traditional Chinese (DGC20180227000001-Taiwan) 9. Fixed LLDP-MED bug where its setting is missing in the output of "show run configuration" (DRU20180306000001-Russia) 10. Fixed DGS-1510-52XMP's Fan & PoE bug issues (DEUR20180228000005, DEUR20180201000003-Europe) 11. Fixed time zone format to function seamlessly with DNA (DI20180131000002-Australia) 12. Fixed trace route TTL error bug (DEUR20180329000001-Europe) 13. Fixed web UI "save configuration" bug issue (DEUR20180403000007-Europe) 14. Fixed CLI command listing displayed in descending order instead of ascending (DI20180528000003-Japan) 15. Fixed command "debug copy tech-support" bug issue (DI20180522000002-Japan) 16. Modified the behavior to include 'clear port description' via checkbox in web UI (DRU20180529000004-Russia) 17. Fixed translation error in Italian (DEUR20180531000005-Europe)

	<ul style="list-style-type: none"> 18. Fixed SNMP server source interface priority error bug (DI20180524000003-Japan) 19. Fixed Voice VLAN & LLDP-MED bug issue (DRU20180409000002-Russia) 20. Fixed "VLAN interface" setting's bug in web UI (DI20180606000003-Japan) 21. Fixed session timeout bug of not timing out & shut session after preset time is exceeded (DEUR20180709000001-Europe) 22. Fixed default admin account re-appearance bug after it was deleted (DUSA20180726000003-USA) 23. Enhance the feature of clone VLAN as well as to support cloning cross units under physical stacking environment (DRU20180806000002-Russia) 24. Fixed coding/programming errors in RADIUS (DI20180803000001-Australia) 25. Fixed & enhanced auto-negotiation issue (DI20170203000004, DI20180302000008-Japan) 26. Fixed IP source guard bug issue (DGC20171121000001-Taiwan) 27. Fixed SNMPv6 response time bug issue (DGC20180619000001-Taiwan) 28. Fixed DHCP Snooping bug issue (DRU20180830000002-Russia) 29. Fixed IPv6 coding error bug issue (DGC20180903000001-Taiwan)
<p>V1.50.021</p>	<ul style="list-style-type: none"> 1. Fixed IPv6 header bug when receiving icmpv6 requests with hop by hop option (DGC20170628000001-Taiwan) 2. Fixed IGMP Snooping bug which freezes the switch (DEUR20170814000001-DEUR, DEUR20170912000003-DEUR) 3. Fixed software bug for showing the wrong DDM information via SNMP (DRU20170907000003-Russia) 4. Fixed firmware's file size display bug between master and slave (physical stacking) when it is upgraded via D-View7 (DI20170915000002-DJP) 5. Fixed DHCP Client bug which caused SSH session to stop functioning (DLA20171011000001-DLA) 6. Fixed DHCP snooping bug when PC's IP address is altered between Static and DHCP (DGC20171121000001-Taiwan)
<p>V1.40.019</p>	<ul style="list-style-type: none"> 1. Fixed some SNMP bugs issue. (DI20150907000007-DJP) 2. Fixed physical stacking bug where master's configuration was overwritten by slave unit (DI20151014000001-DJP) 3. Fixed physical stacking bug when master unit is down, flags on slave and backup master were not updated (DI20151111000001-DJP)

4. Fixed the bug to protect memory allocation to prevent allocated memory blocks from overlapping (DI20151221000005-DJP)
5. Fixed VLAN option 'replace' being accidentally removed from Web UI by software R&D. (DEUR20160530000001-DEUR)
6. Fixed ERPS and LAG software bug when they are both enabled via WebUI. (DEUR20160427000005-DEUR)
7. Fixed sFlow bug not getting a system interface address when interface vlan1 doesn't exist (DRU20160201000001-DRU)
8. Fixed javascript error bug on html for webUI (DEUR20160921000004-DEUR)
9. Fixed some bugs on ACL rules (DI20151019000004-DJP)
10. Fixed webUI's webpage bug (DEUR20170511000002-DEUR)
11. Fixed ERPS ring's bug when 2 switches are rebooted (DEUR20170516000004-DEUR)
12. Fixed CPU's Ingress Backpressure (IBP) limitation by enlarging its IBP threshold (DEUR20170301000006-DEUR)
13. Fixed some bug issues related to:
 14. Difference between running-config and startup-config.
 15. ERPS blank profile cannot be removed.
 16. ERPS won't be in idle status if it is applied with a blank profile.
 17. (DI20151124000002-DJP, DI20170201000004-DJP)
 18. Fixed a SSH security bug (DRU20170120000003-DRU)
 19. Fixed NTP DDOS vulnerability issues (DGC20170704000001-DTW)
 20. Fixed CPU utilization deficiencies in Web UI, related to case (DRU20150818000002-DRU)
 21. Fixed Web UI javascript bug which affected SNMP settings (DRU20151109000002-DRU)
 22. Fixed DHCP Server Screening implementation to limit the global server number to 5 (DGC20150914000005-DTW)
 23. Fixed LBD bug being trapped at CPU without processing (DGC20150828000002-DTW)
 24. Fixed IP addresses' bug for endian formatting (DGC20151019000002-DTW)
 25. Fixed MAC Authentication CLI bug (DRU20151102000005-DRU)
 26. Fixed group name mismatch bug in MIB (DI20151104000006-DJP)
 27. Fixed default VLAN ip address display in Web UI

	<p>(DGC20151109000001-DTW)</p> <p>28. Fixed QoS' meter max rate bug (DEUR20151124000011-DEUR)</p> <p>29. Fixed IP addresses' endian formatting bug when using TFTP server to upload configuration (DRU20151221000003-DRU)</p> <p>30. Fixed physical stacking bug when f/w upgrading is not propagated properly to slaves (DUSA20151203000001-DUSA)</p> <p>31. Fixed software coding bug related to physical stacking and web UI's features (DEUR20160617000002-DEUR)</p> <p>32. Fixed Radius bug for retrieving wrong IP address (DRU20160728000001-DRU)</p> <p>33. TLS 1.2 issues, which is not supported on older f/w. This feature is added in this version (DEUR20160920000003-DEUR)</p> <p>34. Fixed Web UI's HTML coding error (DEUR20170124000001-DEUR)</p>
<p>V1.30.007</p>	<ol style="list-style-type: none"> PoE related software issues are fixed. (DEUR20141105000002-EU, DEUR20141001000006-EU, DUSA20150304000002-USA, DEUR20141119000001-EU, DRU20141212000001-Russia, DGC20150302000001-Taiwan) Switch hung up due to chipsets vendor's SDK with wrong definitions. (DGC20150122000001-Taiwan) Fatal error discovered due to chipsets vendor's SDK with wrong definitions. (DI20141216000001-Japan) Software bug caused physical stacking to malfunction. (DI20150127000004-Japan) Modified software to limit ARP request to CPU at 64Kbps, due to customer's environment with many ARP requests.(DEUR20150224000002-UKI) Resolved the bug where IP address of device information are not updated and synced. (DI20150313000002-Japan) Packet buffer draining issue, Software R&D enhance code to prevent it from happening. (DI20150610000004-Japan)
<p>V1.20.011</p>	<ol style="list-style-type: none"> Modified DHCP Snooping's default value of "per VLAN disabled" to "per VLAN enable" to allow PCs to get IP address via DHCP on a stacking member port's VLAN. (DI20140411000011-Japan) Fixed BPDU bug that caused looping when STP blocking port was changed between stacking units.(DI20140428000007-Japan) Fixed BPDU bug that caused looping when MSTP blocking port was changed

	<p>between stacking units.(DI20140526000003 & DI20140619000008-Japan)</p> <ol style="list-style-type: none"> 4. Fixed the SSH RSA/DSA key generated in stacking master switch which doesn't sync to its slave switches. (DI20140604000001-Japan) 5. Fixed IP address shown in reverse in log when saving configuration via SNMP. (DRU20140512000002-Russia) 6. Fixed CPU interrupt sensitivity software settings that caused the switch to either hung up or lost management respectively. (DEUR20140929000001-EU & DUSA20150325000004-USA) 7. Fixed the switch from entering exception mode when a port is being linked up during MAC authentication. (DGC20140715000003-Taiwan) 8. Fixed IPv6 JWAC bug that did not redirect to authentication page if the interface's IPv6 state is disabled or no IPv6 address has been assigned. (DI20140722000002-Japan) 9. Modify software settings in order for Realtek 8111R NIC card to retrieve IP address from DHCP server faster while transiting via DGS-1510. (DGC20140717000005-China) 10. Enhance support for Intel 82579 NIC card using different driver versions so those DHCP bootp packets are not dropped. (DEUR20140311000007-EU) 11. Fixed DHCP Relay bug that caused PCs not able to get IP address from DHCP server when client & server are in the same VLAN. (DEUR20140902000001-EU) 12. Fixed incorrect VLAN Link status information shown in CLI. (DRU20141203000001-Russia) 13. Fixed the bug of not accepting DHCP relay source address using subnetted network address. DGC20141213000001-Taiwan) 14. Fixed the bug of not accepting configuring switch interface using subnetted network address.(DRU20141218000001-Russia)
<p>V1.10.005</p>	<ol style="list-style-type: none"> 1. DHCP Snooping blocked packets from a VLAN which was not enabled by DHCP Snooping. (DI20140402000002-Japan) 2. Modify the minimum value of command "storm-control unicast level" from 1 to 0. (DI20140325000011-Japan) 3. When DHCP Relay is enabled on a VLAN, DGS-1510 still forward DHCP broadcast packets to the port connected to DHCP server. (DGC20140113000001-China)

V1.00.031	<ol style="list-style-type: none"> Fixed switch rebooting issue in first firmware release. Please see known issues for details. Fixed the safeguard engine bug in first firmware release. Please see known issues for details.
V1.00.029	First release

* D-Link tracking number is enclosed in ()

Known Issues

Firmware Version	Issues	Workaround
V1.70.012	None	
V1.60.012	None	
V1.50.021	None	
V1.40.019	None	
V1.30.007	None	
V1.20.011	<ol style="list-style-type: none"> Switch PoE function will stop delivering power after a while, these are reported in: DEUR20141105000002-EU DEUR20141001000006-EU DUSA20150304000002-USA DEUR20141119000001-EU DRU20141212000001-Russia DGC20150302000001-Taiwan 	It is highly recommended (DGS-1510-28P & DGS-1510-28XMP) to avoid using this firmware. Please kindly contact HQ's Tech Support or PP to get a beta firmware fix, R1.20.B013 that had fixed this issue. R&D fixed this software bug in PoE's Microcontroller settings
V1.10.005	<ol style="list-style-type: none"> After creating a new Access List profile either via CLI or Web UI, the edit button under Access-List was not greyed out in D-View. Per D-View's design SPEC, this is prohibited. IP Source Guard Static Binding table list is created either from CLI or Web UI; it was not editable from D-View. This is a bug. 	These are software bugs of D-View module; they will be fixed in the next version.
V1.00.031	None	

V1.00.029	<ol style="list-style-type: none">1. Under the below scenario, DGS-1510 will reboot: When a switch port (DGS-1510) is set as auto-negotiation, the other connected switch is hardcoded with 100Mbps speed. Then perform cable diagnostic on DGS-1510 and do a "show cable-diagnostic", the switch will reboot.2. When issuing save configuration command, safeguard engine may trigger.	This is a bug, will be fixed in firmware version 1.00.031.
-----------	--	--

* D-Link tracking number is enclosed in ()

Related Documentation

- DGS-1510 Series Web UI Reference Guide Release
- DGS-1510 Series CLI Reference Guide Release
- DGS-1510 Series HW Installation Guide Release