



Firmware Version: 2.10.013
Boot Code Version: 2.10.001
Published: May 7, 2018

The release notes include important information about D-Link switch firmware revisions. Please follow below steps to find version information:

- If you are installing a new switch, please check the hardware version on the device label. Make sure that your switch meets the system requirement of this firmware version. Please Refer to [Revision History and System Requirement](#) for firmware and hardware matrix.
- If the switch is powered on, you can check the hardware version by typing "show version" command or by checking the device information page on the web graphic user interface.

If you plan to upgrade firmware, please refer to the [Upgrade Instructions](#) for the correct firmware upgrade procedure.

For detailed product information, please refer to [Related Documentation](#).

You can also download the switch firmware, D-View modules and technical documentation from <http://tsd.dlink.com.tw>.

Content:

Revision History and System Requirement:	2
Upgrade Instructions:	2
Upgrade using CLI (serial port)	3
Upgrade using Web-UI.....	3
DLMS Instructions:	5
DLMS License Activation by CLI	5
DLMS License Activation by Web-UI.....	6
New Features:.....	7
Changes of MIB & D-View Module:	8
Changes of Command Line Interface:	9
Problem Fixed:	10
Known Issues:	12
Related Documentation:	12

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
2.10.013	2018/5/14	DGS-3630-28SC	A1
		DGS-3630-28TC	A1
		DGS-3630-52TC	A1
		DGS-3630-28PC	A1
		DGS-3630-52PC	A1
2.00.020	2017/10/19	DGS-3630-28SC	A1
		DGS-3630-28TC	A1
		DGS-3630-52TC	A1
		DGS-3630-28PC	A1
		DGS-3630-52PC	A1
2.00.017	2017/9/15	DGS-3630-28SC	A1
		DGS-3630-28TC	A1
		DGS-3630-52TC	A1
		DGS-3630-28PC	A1
		DGS-3630-52PC	A1
1.00.032	2016/3/21	DGS-3630-28SC	A1
		DGS-3630-28TC	A1
		DGS-3630-52TC	A1

Upgrade Instructions:

Note:

- 1. PoE models are supported by firmware version 2.00 and later**
- 2. The 2.00 version is enhanced with security features. DO NOT downgrade the firmware after upgrading to R2.00**
- 3. The switch cannot downgrade to firmware 1.00 when Prom code is 2.00.002**

D-Link switches support firmware upgrade via TFTP server. You can download the firmware from D-Link web site <http://tsd.dlink.com.tw>, and copy the downloaded firmware to the TFTP server folder. Please make sure that the TFTP server is accessible from the switch via networks.

Upgrade using CLI (serial port)

Connect a workstation to the switch console port and run any terminal program that can emulate a VT-100 terminal. The switch serial port default settings are as follows:

- ◆ Baud rate: **115200**
- ◆ Data bits: **8**
- ◆ Parity: **None**
- ◆ Stop bits: **1**

The switch will prompt the user to enter his/her username and password. It should be noted that upon the initial connection, there is **no** username and password by default.

To upgrade the switch firmware, execute the following commands:

Command	Function
copy tftp://LOCATION/SOURCE-URL flash: PATH-FILE-NAME	Download firmware file from the TFTP server to the switch.
boot image	Change the boot up image file.
show boot	Display the information of current boot image and configuration.
reboot	Reboot the switch.

Example:

```
Switch>enable
Switch# copy tftp: //10.73.99.100/DGS3630_Run_1_00_032.had flash: DGS3630_100032.had
```

```
Address of remote host [10.73.99.100]?
Source filename [DGS3630_Run_1_00_032.had]?
Destination filename [DGS3630_100032.had]?
Accessing tftp://10.73.99.100/DGS3630_Run_1_00_032.had...
Transmission start...
Transmission finished, file length 14805356 bytes.
Please wait, programming flash..... Done.
```

```
Switch(config)#boot image DGS3630_100032.had
Switch#show boot
```

```
Unit 1
Boot image: /c:/DGS3630_100032.had
Boot config: /c:/config.cfg
```

```
Switch#reboot
```

```
Are you sure you want to proceed with the system reboot?(y/n) y
Please wait, the switch is rebooting...
```

Upgrade using Web-UI

1. Connect a workstation installed with java SE runtime environment to any switch port of the device.
2. Open the web browser from the workstation and enter the IP address of the switch. The switch's default IP address is 10.90.90.90.


3. Enter administrator's password when prompted. There is **no** username and password by default.
4. To update switch's firmware or configuration file, select **Tools > Firmware Upgrade & Backup > Firmware Upgrade from TFTP** from the banner.

5. Use the drop-down menu to select a unit for receiving the firmware. Select **All** for all units.
6. Enter the TFTP Server IP address.
7. Enter the name of the firmware file located on the TFTP server.
8. Enter the destination path and the desired file name.
9. Click "**Upgrade**" button.
10. Transmission will start and wait until the status is completed by displaying **Done** complete

11. Select the boot up image: click **Management > File System** to open the **File System** window

Drive	Media Type	Size (MB)	File System Type	Label
c:	Flash	1015	FFS	

Click [c:](#) hyperlink, the following window will appear.



Click **Boot Up** button to set a specific runtime image as the boot up image

- Reboot the system: click **Tool > Reboot System**, as shown below; click **Reboot** to reboot the switch. When rebooting the switch, any configuration changes that was made during this session, will be lost unless the **Yes** option is selected when asked to save the settings



DLMS Instructions:

Some D-Link switches support DLMS (D-Link License Management System) feature. With DLMS, you can upgrade your switches to more enhanced edition to get more sophisticated features.

DLMS License Activation by CLI

Command	Function
install dlms activation_code AC-STR [unit UNIT-ID]	This command is used to install an activation code to activate or unlock function on the appliance.
show dlms license [unit UNIT-ID]	This command is used to display license information.

Example:

```
Switch#install dlms activation_code 7xAE1xD7xF4x14x51x69x0o0n
```

Success.

Please reboot the device to active the license.

```
Switch#reboot
```

```
Are you sure you want to proceed with the system reboot?(y/n) y
```

```
Please wait, the switch is rebooting...
```

```
Switch#show dlms license
```


Device Default License : SI
 Current Active License : MI

License Model	Activation Code	Time Remaining
DGS-3630-28TC-SM-LIC	7xAE1xD7xF4x14x51x69x0o0n	No Limited

* expired

DLMS License Activation by Web-UI

1. Connect a workstation installed with java SE runtime environment to any switch port of the device.
2. Open the web browser from the workstation and enter the IP address of the switch. The switch's default IP address is 10.90.90.90.
3. Enter administrator's password when prompted. There is **no** username and password by default.
4. To update switch's firmware or configuration file, select **Tool > DLMS Settings** from the banner.




5. Enter the Activation Code and select unit of stack then click **Apply** to activate the assigned switch.



6. To reboot the switch, select **Tools > Reboot System** from the banner.
7. Select **Yes** and click **Reboot** button to reboot the switch.





New Features:

Firmware Version	New Features
2.10.013	<ol style="list-style-type: none"> 1. Support M-LAG 2. Removing Java from web page 3. SSH support SHA 256 4. Enlarge Radius key length to 255 characters 5. TACACS+ accounting supports service type in packet format 6. Support to enable or disable static router MAC address's timeout 7. Support to specify IP address as SSH source address 8. Support OpenFlow 1.3 (only supported CLI)
2.00.020	<ol style="list-style-type: none"> 1. Support unicast and multicast IP address on PIM control message
2.00.017	<ol style="list-style-type: none"> 1. Add DGS-3630-28PC/52PC PoE new models 2. Support PD Alive feature for PoE models 3. Support user-defined alias 4. Support enabling or disabling the link-change log 5. The log/debug message can be displayed to remote session via Telnet/SSH session. 6. Support Exec Banner 7. User can configure C-tag's priority in VLAN Translation feature 8. Support session timeout when login to another device without disconnecting current session. 9. The syslog supports ARP Spoofing Prevention 10. Support IPv6 data-glean 11. LACP load balance supports MPLS label. 12. Support static MLD group 13. Support PIM-DM for IPv6 14. Support OSPF process ID 15. IP multicast table lookup supports to configure IP mode or MAC mode 16. Super VLAN supports IPv6 17. The Zone-defense feature can be configured by CLI and Web GUI now. 18. The LSA size enlarges from 4032 bytes to 16383 bytes 19. Support VLAN interface for IP Source Guard 20. Support SFTP Client 21. Support displaying 802.1p queue statistics per port information in CLI 22. The port interface supports uptime parameter in CLI 23. Support TLS 1.2

	<ul style="list-style-type: none"> 24. Support RFC4884 (Extended ICMP to Support Multi-Part Messages) 25. User is able to configure source IP address in LDP hello message 26. Encrypting the password in HTTP connection 27. Support announcing loopback interface as OSPFv3's source IP interface. 28. Changing output's format when executing show running config command
1.00.032	First Release

Changes of MIB & D-View Module:

The new features of MIB file are also included in the corresponding D-View module. Please download the D-View module from <http://tsd.dlink.com.tw>. For detailed changes of MIB content, please refer to the modification history in each MIB file.

Firmware Version	MIB File	New Features
2.10.013	DLINK-MLAG-MIB	M-LAG
	DLINKSW-SSH-MIB	SSH support SHA 256
	DLINKSW-AAA-SERVER-MIB	Enlarge Radius key length to 255 characters
	Support to specify IP address as SSH source address	DLINKSW-SFTP-CLIENT-MIB
	Support to enable or disable static router MAC address's timeout	DLINKSW-IP-EXT-MIB
2.00.017	POWER-ETHERNET-MIB.mib DLINKSW-POE-MIB.mib	Add DGS-3630-28PC/52PC PoE model
	DLINKSW-POE-MIB.mib	PD alive for PoE models
	DLINKSW-CLI-ALIAS-MIB.mib	Support user-defined alias
	DLINKSW-SWITCHPORT-MIB.mib	Support enabling or disabling the link-change log
	DLINKSW-SYSLOG-MIB	The log/debug message can be displayed to remote session (Telnet/SSH)
	DLINKSW-VLAN-TUNNEL-MIB.mib	User can configure C-tag's priority in VLAN Translation feature

	DLINKSW-ASP-MIB	The syslog supports ARP Spoofing Prevention
	DLINKSW-IPV6-SNOOPING-MIB	Support IPv6 data-glean
	DLINKSW-LACP-EXT-MIB	LACP load balance supports MPLS label
	DLINKSW-MGMD-EXT-MIB	Support static MLD group
	PIM-STD-MIB IPMCAST-MIB DLINKSW-PIM-EXT-MIB	Support PIM-DM for IPv6
	OSPF-MIB DLINKSW-OSPFV2-MIB	Support OSPF process ID
	DLINKSW-IPMCAST-EXT-MIB.mib	IP multicast table lookup supports to configure IP mode or MAC mode
	DLINKSW-SUPER-VLAN-MIB.mib	Super VLAN supports IPv6
	DLINKSW-IP-SOURCE-GUARD-MIB DLINKSW-IPV6-SRC-GUARD-MIB	Support VLAN interface for IP Source Guard
	DLINKSW-SFTP-CLIENT-MIB	Support SFTP Client
	DLINKSW-QOS-MIB	Support displaying per port's 802.1p queue statistics in CLI
	DLINKSW-SSL-MIB	Support TLS 1.2
	rfc1213.MIB	Support displaying IP address of VRF interface in MIB file
	DLINKSW-STACK-MIB.mib	Support dStackInfoStartPort and dStackInfoPortRange in MIB file
	DLINKSW-MPLS-MIB	Support configuring source IP address in LDP hello message
1.00.032	First Release	

Changes of Command Line Interface:

The section below only shows command line changes that may bring backward compatibility issues with configuration settings for previous version of firmware. Any new feature commands that do not have backward compatibility issues are not included in the below section.

Firmware Version	Changes
2.10.013	None
2.00.020	None
2.00.017	None
1.00.032	First Release

Problem Fixed:

Firmware Version	Problems Fixed
2.10.013	<ol style="list-style-type: none"> Fixed the issue that displaying “MSTP_Rx_Syn_pkt --- > Queue is Full!” continuously when typing "sh run a" (DI20171201000001) Fixed the issue that master unit didn't get the correct STP's message from slave unit (DI20171106000002) Fixed the issue that DGS-3630 does not balance IP traffic via LACP (DRU20171127000001) Fixed the issue that ARP entry is disappeared when VLAN interface and VRF interface are the same IP address (DI20171122000006) Fixed the issue that incorrect timestamp when PTP mode is boundary (DI20171114000004) Fixed the issue that default community public and context map would be overridden after the system is rebooted (DI20171106000004) Fixed the issue IP helper settings are disappeared when typing sh run interface vlan (DRU20171031000004) Fixed the issue DGS-3630 cannot linkup the 10G port with DEM-431 C1 (DI20171020000001) Fixed the issue that DGS-3630 doesn't display logging source-interface for management interface (DI20171026000005) Fixed the issue that the switch is taken much time to establish stacking topology, it make CPU loading is 100% (DI20171025000004) Fixed the issue that static multicast ARP entry is incorrect when duplex ring stacking and NLB are enabled (DI20170817000001) Fixed the issue that displaying ERPS setting's error message when VLAN port is trunk (DI20170816000005) Fixed the issue that Public and Private of SNMP community will be retrieved after the switch is rebooted(DI20170809000003) Fixed the issue that ACL cannot filter user's packets (DRU20170719000004) Fixed the issue that DGS-3630 only forwards first VLAN of VLAN list range in in VPLS local attachment circuit, others cannot forward (DRU20170727000006) Fixed the issue that using the different interface as source IP to non-connected IP segment for Radius and Tacacs+ (DI20160728000008) Fixed the issue that syslog server is used wrong IP address as source interface (DI20160629000005) Fixed the issue that user cannot create BGP network with mask /27 and longer (DRU20180125000001) Fixed the issue that the command “clear counter all” does not clear Linkchange counter (DEUR20180130000004) Fixed the issue that ifInDiscards counter of 10G port is too high in customer's network (DEUR20180129000003) Fixed the issue that LLDP information is incorrect after typing “show run”

	<p>(DI20180126000006)</p> <ol style="list-style-type: none"> 22. Add warning message when erasing IP address of VRF instance (DI20180209000005) 23. Fixed the issue that CPU loading is high in customer's network (DGC20171226000001) 24. Fixed the issue that striping outer tag of double VLAN when Q-in-Q is enabled (DRU20180221000004) 25. Fixed the issue that DGS-3630 didn't respond SNMP request to VRF interface when upgrading firmware from 1.00 to 2.00 (DI20180227000001) 26. Fixed the issue that LLDP management address is inconsistent with running-config and lldp run (DRU20180302000001) 27. Fixed the issue that DGS-3630 cannot get IPv6 address from RA (Router Advertisement) router (DGC20180302000003) 28. Fixed the issue that stacking and LACP are configured, the link partner will detect the loop after switch is reboot (DGC20170425000001) 29. Fixed the issue that DoS prevention Blat feature doesn't drop UDP packet (DI20180302000001) 30. Fixed the issue that configuration init state is incorrect after Master unit is rebooted in stacked mode (DI20180420000004)
2.00.020	<ol style="list-style-type: none"> 1. Fixed the issue that the switch cannot be rebooted correctly after enabling SNMP and upgrading firmware to 2.00 (DI20170919000001) 2. Fixed the issue that the switch cannot be rebooted correctly after enabling SNMP with customer's configuration file (DRU20171002000001)
2.00.017	<ol style="list-style-type: none"> 1. Fixed the issue that LBD cannot work on VPLS interface (DRU20170524000003) 2. Fixed the issue that the switch will display the error message when configuring specific MAC address for DHCP server binding (DGC20170518000002) 3. MPLS LSP is not working until LDP session is renegotiated (DI20170313000007) 4. Removing half duplex on port's description (DEUR20170405000002) 5. Improved performance issue when STP and LACP is running at the same time in stacking mode (DEUR20170405000002) 6. Fixed the issue that LDP Hello packets from other device are not forwarded to the same VLAN when enabling LDP (DI20170203000006) 7. Fixed the issue that HTTP Server has not been synchronized to slave unit when enabling secure HTTP server (DI20170203000006) 8. Fixed the issue that the switch will auto reboot when LACP keeps link up and down in ISIS environment (DI20170206000002) 9. Fixed the issue that the error message "ERROR: Get ltm information on other box failed." will keep on appearing on console (DI20170113000011) 10. Fixed the issue that the console may be frozen during executing "debug show tech" command When CFW is enabled (DI20170113000011) 11. Fixed the issue that the switch will not redirect to WAC logout page in stacking mode (DI20161108000016) 12. Fixed the issue that the configuration which was copied to TFTP server by "copy running-config tftp: //X.X.X.X/XX.txt" command is not the same as "show running-config", "show running-config effective", or " show running-config all" (DI20161116000002) 13. Fixed the issue that the console sometimes may be frozen after WAC Authentication (DI20160930000001) 14. Fixed the issue that the switch will not send ISIS Hello packet when new Master be elected (DI20161019000003) 15. Fixed the issue that inDiscard counter of port-channel is always zero even there're real traffic injected (DI20161006000003) 16. Fixed the issue that there might be some characters missing when typing in CLI and Web UI (DI20160921000002) 17. Fixed the issue that IPv6 PIM hello packets are dropped when MLD snooping is enabled and multicast filtering mode is set to forward all/unregistered packets. (DI20160921000004)

18. Fixed the issue that syslog used wrong IP address as the source interface (DI20160830000005) (DI20160530000005)
19. Fixed the issue the UDP 8021/8022 ports are opened by default, although the associated service is disabled (IMA20160816000001)
20. Fixed the issue that the VLAN interface does not linkup after reboot, if VLAN ID is over 255 and belongs to Multiple Spanning Tree Instances (DI20160905000004)
21. Fixed the issue that the switch will not send SNMP traps after clearing the arp table or reboot the switch (DI20160728000005)
22. Fixed the issue that the switch will respond incorrect DHCP ACK packets when the switch is received DHCP request from different IP segment (DI20160518000004)
23. Fixed the issue that the packets are not forwarded among stacking members when stacking topology is changed from Ring to Chain and then back to Ring again (DI20160705000001)
24. Fixed the issue that the backup master won't send any packets through the management interface (DI20160621000005)
25. Fixed the issue that the switch sends an incorrect specific query when switch receiving both IGMPv3 report packet and IGMPv2 leave packet at the same time (DI20160616000003)
26. Fixed the issue that the switch does not send Hot Insertion log in IPv6 syslog server (DI20160525000004)
27. Fixed the issue that sometimes the switch is rebooted automatically when executing "no service dhcp" command (DI20160518000002)
28. Fixed the issue that the QoS scheduler configuration is incorrect on combo port (DI20160511000002)
29. Fixed the issue that the switch will display an error message when configuring specific IP address (DI20160428000007)
30. Fixed the issue that the switch's FDB aging mechanism is incorrect (DI20160405000008)
31. Fixed the issue that the switch does not create MPLS forwarding table for connected interface when LDP is enabled (DI20160407000005)

1.00.032 First Release

* D-Link tracking number is enclosed in ()

Known Issues:

Firmware Version	Issues	Workaround
2.10.013	None	None
2.00.020	None	
2.00.017	The switch cannot be rebooted correctly sometimes after enabling SNMP	<ol style="list-style-type: none"> 1. Clearing configuration file by typing Shift + 6 2. Upgrading firmware to 2.00.020
1.00.032	None	

Related Documentation:

- DGS-3630 Series CLI Reference Guide Release 2.10
- DGS-3630 Series CLI Reference Guide Release 2.10 (OpenFlow)
- DGS-3630 Series Hardware Installation Guide Release 2.10
- DGS-3630 Series Web UI Reference Guide Release 2.10