



Firmware Version: 1.03.014
Boot Code Version: 1.00.002
MIB Version: 1.03.014
Published: Apr. 1, 2026

These release notes include important information about D-Link switch firmware revisions. Please verify that these release notes are correct for your switch:

- If you are installing a new switch, please check the hardware version on the device label; make sure that your switch meets the system requirement of this firmware version. Please refer to [Revision History and System Requirement](#) for detailed firmware and hardware matrix.
- If the switch is powered on, you can check the hardware version by typing "show switch" command via Telnet or by checking the device information page on the web graphic user interface.
- If you plan to upgrade to the new firmware release, please refer to the [Upgrade Instructions](#) for the correct firmware upgrade procedure.

For more detailed information regarding our switch products, please refer to [Related Documentation](#).

You can also download the switch firmware and technical documentation from <http://tsd.dlink.com.tw>.

Content:

Upgrade Instructions:	4
Upgrade using CLI (via Console or Telnet)	4
Upgrade using Web-UI	5
Upgrade using D-Link Network Assistant App	8
New Features:	12
Changes of MIB	12
Changes of Command Line Interface:	13
Problem Fixed:	13
Known Issues:	16
Related Documentation:	18

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version	MD5-CHECKSUM
Runtime: V1.03.014 Boot: 1.00.002	21-Mar-2026	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	5bed2b8b1e5f85b38af5ed7acfb107b
Runtime: V1.03.B012 Boot: 1.00.002	3-Dec-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B011 Boot: 1.00.002	11-Nov-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B010 Boot: 1.00.002	21-Oct-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B009 Boot: 1.00.002	14-Aug-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B008 Boot: 1.00.002	11-July-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B007 Boot: 1.00.002	10-Apr-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.03.B006 Boot: 1.00.002	27-Feb-2025	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.02.B003 Boot: 1.00.001	15-Jan.-2025	DMS-1250-10S/ 10SP/12TP	A1	
Runtime: V1.03.005 Boot: 1.00.002	25-Dec-2024	DMS-1250-10S/ 10SP/12TP/10SP L/12/18/18P/28/ 28P	A1	
Runtime: V1.02.002 Boot: 1.00.001	23-May.-2024	DMS-1250-10S/ 10SP/12TP/10SP L	A1	
Runtime: V1.00.010 Boot: 1.00.001	11-Sep.-2023	DMS-1250-10S/ 10SP/12TP	A1	
Runtime: V1.00.008 Boot: 1.00.001	13-June.-2023	DMS-1250-10S/ 10SP	A1	

Upgrade Instructions:

D-Link Switches support firmware upgrade via TFTP server. You can download the firmware from D-Link web site <http://tsd.dlink.com.tw>, and copy the downloaded firmware to the TFTP server folder. Please make sure that the TFTP server is accessible from the switch via networks.

Upgrade using CLI (via Console or Telnet)

1. If you use Telnet, please make sure the network connection between the switch and PC is active. If you use Console, please use "Serial to USB" cable connect switch console port and PC USB interface.

2. Via Telnet: Use software that supports telnet, for example, HyperTerminal or Telnet command in Microsoft Windows, to connect to the switch. If you are using Telnet command, type the command followed by the switch IP address, eg. *telnet 10.90.90.90*.

Via Console: Use software that supports serial communication, for example, HyperTerminal, Putty or SecureCRT to connect switch console port with band rate **115200**.

3. The logon prompt will appear.

The switch will prompt the user to enter his/her username and password. Both the default user name and password are **"admin"**.

The switch not support to upgrade current startup image id, will automatically upgrade to another image id.

To upgrade the switch firmware, execute the following command:

Command	Function
copy tftp://LOCATION/SOURCE-URL	Download firmware file from the TFTP server to the switch.

When completing firmware upgrade, the following messages will pop up.

```
Switch# copy tftp://10.90.90.99/DMS-1250-SERIES-V1-00-008-FW.hex
TFTP Firmware Upgrade processing.....Do not power off!!
Firmware upgrade successfully!
Switch#
```

4. Select image id that was successful upgrade firmware as next start up image id, reboot system and execute the following command to check the firmware version and switch's information.

Command	Function
show switch	Display the information of current firmware and boot version.
show firmware	Display the information of the image or firmware.

Example:

```
1. Switch# copy tftp://10.90.90.99/DMS-1250-SERIES-V1-00-008-FW.hex
TFTP Firmware Upgrade processing.....Do not power off!!
Transferring firmware..... 10%
```

Firmware upgrade successfully!
Switch#

2. Switch# **show switch**

Device Information

```
Device Type      : DMS-1250-10S Multi-Gigabit Ethernet Smart Managed Switch
System Name     : Switch
System Location  :
System Contact   :
Boot PROM Version : 1.00.001
Firmware Version : V1.00.008
Hardware Version : A1
MAC Address     : 00-12-55-99-00-78
IP Address      : 10.90.90.90
Mask            : 255.0.0.0
Gateway         : 0.0.0.0
System Time     : 01/01/2023 00:00:52
Serial Number    : QQABC12345600
Switch#
```


3. Switch# **show firmware**

Image ID	Version	Size(B)	Update Time
*1c	V1.00.008	13078080	01/01/2023 00:00:00
2	V1.00.008	13078080	01/01/2023 00:00:00



c : Current boot up firmware
* : Boot up firmware

Upgrade using Web-UI


1. Connect a workstation to any switch port of the device.
2. Open the web browser from the workstation and enter the IP address of the switch. The switch's default IP address is 10.90.90.90.
3. Press OK to login. Both the username and password are **"admin"** by default.
4. To update switch's firmware or configuration file, select **Tools > Firmware Backup & Upgrade** from the banner.




5. Two methods can be selected : **HTTP** or **TFTP**
6. Select **Firmware Update from HTTP** to upgrade the firmware to or from your local drive of PC.




- a. Click **“Choose File”** to browse your inventories for a saved firmware file
- b. Click **Upgrade** after selecting the firmware file you want to upgrade



- c. It will be download the firmware file to DUT.
- d. When download success, do not power off, and will continue process upgrading (write firmware to flash).




- e. Wait until the **“Firmware Upgrade Successful”** message pops up.




7. Select **TFTP** to upgrade the firmware to or from a remote TFTP server.




- Enter the TFTP server IP and the URL of the firmware file located on the TFTP server.
- Click **Upgrade** after selecting the firmware file you want to restore.
- It will be download the firmware file to DUT.



- When download success, do not power off, and will continue process upgrading (write firmware to flash).




- Wait until the firmware upgrade ends.




Upgrade using D-Link Network Assistant App

1. Connect a workstation installed with java SE runtime environment to any switch port of the device. Install DNA App in Web Store of Chrome Browser.
2. Execute D-Link Network Assistant App.



3. Click Refresh button to search target switch




4. Move mouse to target device entry, then click "Upgrade firmware" button into upgrade firmware page

Default Workspace (Online / Offline: 1 / 0)


Type / Status	Auth.	System Name	IP Address	MAC	Model	SNMP	FW Ver.	SN	System Time	IP Mode	HW Ver.	Protocol Ver.
		Switch	10.90.90.90	00-12-55-99-00-78	DMS-1250-105		V1.00.008	QQABC12345600	2023/01/01 04:22:36			

Upgrade firmware


5. Click Browse button and select the firmware file (Model name- FW version .hex) on your local hard drive.




6. Click "Upgrade now" button to start firmware upgrade.



7. Wait until firmware upgrade finished.



8. The DNA pop an information to notify firmware upgrade status. Also can get firmware upgrade status from "Device journey" page.



New Features:

Firmware Version	New Features
V1.03.014	Support Nuclias Unity
V1.03.B011	Support LLDP-MED Network Policy
V1.03.005	1. Support new model 12/18/18P/28/28P 2. Support UIS-SSH-v1.05 3. Support UIS-TLS-v1.02 4. Openssl upgrade to 1.1.1w
V1.02.002	1.VLAN QinQ 2.DHCPv4/v6 and local relay with option82 support 3.ZTP + DHCP Auto-image 4.non-WAC Radius CoA/DM 5.ISM Vlan 6.DNC
V1.00.010	NONE
V1.00.008 (Not formal release)	First Release

Changes of MIB :

For detailed changes of MIB content, please refer to the modification history in each MIB file.

Mib Version	MIB File	New Features
V1.03.B011	DMS-1250-SERIES-V1.03.B011.mib	LLDP-MED Network Policy
V1.03.005	DMS-1250-SERIES-V1.03.005.mib	1.UIS-SSH-v1.05 2.UIS-TLS-v1.02
V1.02.002	DMS-1250-SERIES-V1.02.002.mib	1.VLAN QinQ 2.DHCPv4/v6 and local relay with option82 support 3.ZTP + DHCP Auto-image 4.ISM Vlan 5.DNC

V1.00.010	DMS-1250-SERIES-V1.00.010.mib	Remove statPortCountCarriSen,statPortCo untSQETestErr,statCountersrxMult icastDropPkts,statCountersifInUn knownProtos,statCounterstxDelay ExceededDiscards
V1.00.008 (Not formal release)	DMS-1250-SERIES-V1.00.008.mib	First Release

Changes of Command Line Interface:

The section below only shows command line changes that may bring backward compatibility issues with configuration settings for previous version of firmware.
Any new feature commands that do not have backward compatibility issues are not included in the below section.

Firmware Version	Changes
V1.03.B011	Support 'lldp med-tlv-select network-policy'
V1.03.005	1.add commands following spec UIS-SSH-v1.05 2.add commands following spec UIS-TLS-v1.02
V1.00.010	NONE
V1.00.008 (Not formal release)	First Release

Problem Fixed:

Firmware Version	Problems Fixed
V1.03.014	1. QA2 Unity Server 0.7.5-418 test result is fail, Unity Client info cannot display IP address. 2. DMS-1250-18p will crash after start Local Devie lights up all LEDs 3. DMS-1250-28P/28 Local Devie lights up all LEDs in green feature invalid after start then stop. 4. QA2 Unity Server 0.7.8-460 test result is fail, the Switch cannot be discover via APP after delete adopt Switch from
V1.03.B012	1. [HQ20251104000002][D Track DMS-1250 1.03.B010 HQ20251104000002] IP interface not coming up[DI20251031000002-Japan]
V1.03.B010	1. [HQ20250826000011][DMS-1250/1.03.B009] Wrong ifSpeed/ifHighSpeed on a channel for 2.5Gbps. / relate to DI20250826000001[DI2025082600000 2. [HQ20250826000009] [DMS-1250/1.03] Wrong ifSpeed for 2.5Gbps.[DI20250826000001-Japan] 3. [HQ20250827000003][DMS-1250/v1.03.B009] [SSH] ERROR: Get the session id error! in SSH w/ Public Key.[DI20250826000008-Japan] 4. [HQ20250828000002][DMS-1250] Question about DHCP and TFTP client

	in factory default settings[DI20250827000004-Japan] 5. [HQ20250901000005] [D-Track DMS-1250 v1.03.B009]Impossible to enable guest VLAN[DI20250829000001-Japan] 6. [HQ20250922000002][DMS-1250/v1.03.B009] Unable to ping vlan21 IP interface[DI20250919000002-Singapore]
V1.03.B009	1. [HQ20250717000002] [IMA20250127000001-India]SSH tables are not cleared. 2. [HQ20250711000009] [DI20250710000004-Japan] DHCP relay does not work. 3. [HQ20250626000004] [DMS-1250/v1.03.B007] CLI VLAN setting issue. 4. [HQ20250731000005] [DMS-1250 (v1.03.B008) User account admin "password" modify failed [DI20250730000 001-Japan].
V1.03.B008	1. [HQ20250613000002] [DMS-1250/1.03] a wrong err msg for ipv6 route default.[DI20250612000005-Japan] 2. [HQ20250612000005] [DMS-1250/1.03] performs a periodic which is already deleted in time-range.[DI20250612000002-Japan] 3. [DBG25040261] when copying and pasting the config that starts with configure terminal, SSH session and WEBGUI will hang up. 4. [HQ20250611000007] DMS-1250-28P fan off mode behavior does not fit spec. 5. [HQ20250605000003] [DMS-1250/1.03] 802.3 Extension TLV in LLDP. (MAC/PHY)[DI20250605000004-Japan] 6. [HQ20250613000006] [D-Track] DMS-1250 doesn't allow to disable for logging source-interface w/o the src int via only WebUI. 7. [HQ20250617000004] [DMS-1250/1.03] The port list in DSCP List are arranged by port model on its WebUI.[DI20250616000002-Japan] 8. [HQ20250626000004] [DMS-1250/v1.03.B007] CLI VLAN setting issue
V1.03.B007	HQ20250324000002 Disbale SNMP private [DMS-1250][DEUR20250317000001-Central Europe]
V1.03.B006	1. HQ20241220000006 [DMS-1250/1.02] PD alive doesn't work in IPv6.[DI20241219000003-Japan] Include V1.02.B003 Fixed issue 2. HQ20241216000002 Console frozen[DI20241213000001-Japan] 3. [DMS-1250/1.02] shows a wrong err msg in case of port-channel. / same as DI20240924000001[DI20241210000002-Japan] 4. [DMS-1250/1.02] gets influence of ipv6 acl in line tel in ssh. / same as DI20240919000003[DI20241210000001-Japan] 5. [DMS-1250/1.02] Invalid firmware via https. / same as DI20240909000001 6. [DMS-1250/1.02] doesn't change native vlan properly. 7. [DMS-1250/1.02] doesn't show an err msg on its CLI when asymmetric-vlan can't be enabled.[DI20241219000001-Japan] 8. [DMS-1250/1.02] 'source-interface' doesn't work in SNMP Trap in IPv6.[DI20241223000001-Japan]
V1.03.005	1. VBG23060012 Partner portNo and portPri of LACP Neighbor Information cannot display information. 2. DBG23080297 [AAA][Auto][SNMP] DUT auto creating tacacs server group via SNMP 3. DBG23080317 [AAA][Auto] cannot delete AAA default login method when set all none 4. DBG23080266 [WebUI][Auto] Unable to login to DUT and UI gets stuck at loading. 5. VBG23090001 [Auto][TSD1SW_L2_Unicast_FDB]FDB-Change PVID of port which has been added into FDB entry 6. DBG23070092 [802.1X] When Authentication Server Failover, client

	can't pass authentication by local DB 7. VBG23060010 DMS-1250 SFP interface via 10G Fiber to Copper transceiver will link up without cable, and 10G transceiver will blinking. 8. DBG24060346 [Configure LLDP Forward][DMS-1250]PC can not capture LLDP packets from DUT1 9. DBG24060401 [DMS-1250 1.02.002][SNMPv3]Crash issue on SNMPv3 Test
V1.02.B003	1. HQ20241216000002 Console frozen[DI20241213000001-Japan] 2. [DMS-1250/1.02] shows a wrong err msg in case of port-channel. / same as DI20240924000001[DI20241210000002-Japan] 3. [DMS-1250/1.02] gets influence of ipv6 acl in line tel in ssh. / same as DI20240919000003[DI20241210000001-Japan] 4. [DMS-1250/1.02] Invalid firmware via https. / same as DI20240909000001 5. [DMS-1250/1.02] doesn't change native vlan properly. 6. [DMS-1250/1.02] doesn't show an err msg on its CLI when asymmetric-vlan can't be enabled.[DI20241219000001-Japan] 7. [DMS-1250/1.02] 'source-interface' doesn't work in SNMP Trap in IPv6.[DI20241223000001-Japan]
V1.02.002	1. DBG24030605 [IP Interface][DMS-1250-10SPL][1.01.P006]DMS-1250 vlan interface setting is missing 2. DBG24040006 [ISM][DMS-1250-10SPL][1.01P006]ISM VLAN cannot work when the multicast client is on different VLANs. 3. DBG24040015[ISM][DMS-1250-10SPL][1.01.P006]Cannot display the table of ip igmp snooping statistics vlan 4. DBG23080297[AAA][Auto][SNMP] DUT auto creating tacacs server group via SNMP 5. DBG23080266[WebUI][Auto] Unable to login to DUT and UI gets stuck at loading. 6. DBG23080317[AAA][Auto] cannot delete AAA default login method when set all none 7. VBG23060010 DMS-1250 SFP interface via 10G Fiber to Copper transceiver will link up without cable, and 10G transceiver will blinking. 8. DBG23090258[Voice VLAN][Auto] unable to identify device when set voice vlan mode as manual
V1.00.B014	1. [HQ20240416000008] [DMS-1250/1.00] shows 'SNMP Error Inconsistent Value.' in 'sw tr al vl'.[DI20240416000002-Japan]
V1.00.B013	1. HQ20240326000002 [DMS-1250/1.00] 'terminal length' doesn't work w/ 'mac-address-table static' properly.[DI20240325000003-Japan] 2. HQ20240326000003 [DMS-1250/1.00] 'test cable-diagnostics' causes hot-sby and detaching from Link Aggregation Group.[DI20240326000001-Japan] 3. HQ20231220000003 [DMS-1250/1.00] 'sh run' and 'copy run sta' causes T/C.[DI20231218000012-Japan]
V1.00.B012	1. HQ20231215000005 [DMS-1250/1.00] doesn't send SNMP traps w/ 'snmp-server source-interface traps'. / same as DI20230905000004[DI20231215000001-Japan] [Medium] 2. HQ20240104000014 [DMS-1250/1.00] shows 16386 as the total of its fdb and all 0 as int vlans.[DI20240104000003-Japan] 3. HQ20240104000012 [DMS-1250/1.00] !rtkErr: [RT_ERR] dal/longan/dal_longan_l2.c:3729: In function 'dal_longan_l2_addr_add'[DI20240104000004-Japan] [Medium] 4. HQ20240105000007 [DMS-1250/1.00] NPERR CmNpVlanHwVlanPortAdd(5768): CmNpVlanHwVlanPortAdd: incorrect

param u2TagMode=3 / relate to
DI20231218000007[DI20240105000001-Japan] [Medium]

Known Issues:

Firmware Version	Issues	Note
V1.00.008 ~ V1.03.014	1. VBG23030018 [FW 1.00.001/Boot: 1.00.001] Test Result is fail. DMS-1250 Max MAC address table size is 16383, increment learning is OK, but random learning just 15154 (loss rate 7.5%)	(HW Limitation)
	2. VBG23020067 DUT should not re-sync when adding LACP same group member port.(design limitation)	(design limitation)
	3. VBG23010003 PC2 still can receive packets from PC1,when enable DOS Ping To Death attack	(HW Limitation)
	4. VBG23020015 [FW 1.00.001/Boot: 1.00.001] Test Result is fail, DMS-1250 A1 Series traceroute result will be affect when lots ARP packets sending in the same time.	(design limitation)
	5. VBG23030053 [FW 1.00.002/Boot: 1.00.001] Test Result is fail. DMS-1250 Series Voice VLAN dynamic member forward Voice VLAN ID packets need 2nd packets, the first one packets cannot change to Voice VLAN	(design limitation)
	6. VBG23020001 [FW 1.00.001/Boot:1.00.001] Test Result is fail. when T-test2 timeout will cause T-test1 packets flooding some packets to others ports.	(design limitation)
	7. VBG22120073 [FW 1.00.001/BOOT 1.00.001] test result is fail. DMS-1250 STP and LBD global cannot enable at the same time, that does not fit based- on port state check rule.	(design limitation)
	8. VBG23060009 PoE chip RTL8238B, when provide power to Legacy PD, classification will show "class 0".	(HW Limitation)

9. VBG23040014	DMS-1250-10SP LED Mode change button, sometimes cannot change mode after we push button.	(HW Limitation)
10.DBG23070110	[DDM] Wrong Command Mode for 'snmp-server enable traps transceiver-monitoring'.	(design limitation)
11.VBG23050034	Cable Diag test shows incorrect results.	(Limitation)
12.VBG23020056	[FW 1.00.001/Boot: 1.00.001] Test Result is fail, DUT cannot reply ping broadcast address request.	(Know issue)
13.DBG23080282	[Auto] MAC Address is changed after deletion of another IP Interface and save reboot.	(Limitation)
16. VBG24040014	DMS-1250 does not sync DNC set configuration of Time Range as Many Weekdays.(If it is a consecutive number of days, there is no such problem).	(Spec Issue)
17. DBG23090225	[1.00.010][Auto][TSD1SW_Error_Recovery]002 4_Error Recovery - Port security - Basic Function	(Know issue)
18. VBG24010062	[DKP0911064-91]DHCP Relay-Received the Relayed DHCP packets,in this test when Disabled the DHCP unicast relay the DHCP client cannot Forward packet to DHCP server	(Know issue)
19. DBG23090257	[Auto][TSD1SW_PING][DMS-1250][1.00.010]PING - To Unknown/ inexistence host	(Know issue)
20. DBG23090256	[Auto][TSD1SW_L2_Mirror]Port Mirroring - Add/Delete only Source port or Target port	(HW Limitation)

	21. DBG24010086 [DMS-1250-12TP/HW:A1]When setting a number out of range in MIB, the error message displays "Unknown error".	(Know issue)
	22. VBG24120039 Logging in to an ssh will use two sessions. (tool:MobaXterm)	(Know issue)

Related Documentation:

- DMS-1250 Series A1 User Manual
- DMS-1250 Series Getting Started Guide