



Firmware Version: V1.12
Prom Code Version:
Published Date: 2015/10/26

Content:

Upgrading Instructions:..... 2

New Features:..... 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/5/22	DCS-3010	A1
V1.10	2013/10/23	DCS-3010	A2
V1.11	2014/5/6	DCS-3010	A2
V1.12	2015/10/26	DCS-3010	A2

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website.
2. Log-in camera web UI and enter **Setup/Maintenance/Firmware upgrade**.
3. Click **Browse** and specify the firmware file "DCS-3010_v1.10.01_ww".
4. Click **Upgrade**. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V1.00	First released
V1.10	Schedule Device Reboot

Problems Fixed:

Firmware Version	Problems Fixed
V1.00	First released
V1.10	<p><u>D-Lab bug</u></p> <ol style="list-style-type: none"> 1. DCS-3010 couldn't be set a 36 characters password by SetupWizard SE v1.05 and its admin page [Bug ID DBG13070113, DBG13070112] 2. DCS-100 couldn't recognize the DCS-3010 by Manual Insert with Auto Detect [Bug ID: DBG13070089] 3. Time and Date of DCS-3010 couldn't synchronized with a NTP server after the Internet connection recovered [Bug ID: DBG13010350] <p><u>D-Track bug</u></p> <ol style="list-style-type: none"> 1. MJPEG boundary parameter is missing [Bug ID: DEUR20130523000005] 2. IE crash on Win7 64 [Bug ID: HQ20130523000003] <p><u>Others</u></p> <ol style="list-style-type: none"> 1. Security hole issue 2. Enable RTSP Authentication default. 3. SetupWizard DHCP and static IP setting issue.
V1.11	<ol style="list-style-type: none"> 1. Samba always recording issue. 2. Integration issue with DNR-2060-08P 3. Audio issue with DCS-100

	4. Access PPPoE issue 5. Tamper Detector function
V1.12	1. Change new digital signature 2015.

Known Issues:

Firmware Version	Known Issues
V1.00	N/A
V1.10	1. Camera would reboot unexpectedly during endurance test. [D-Lab Bug ID: D20131003001] 2. Some snapshots on FTP server would be in 0 KB. [D-Lab Bug ID: DBG13090018]

Related Documentation:

N/A