



Firmware Version: 2.07rc031

Published Date: 2016/03/23

Content:

Upgrading Instructions:.....	2
Upgrading by using Web-UI.....	2
New Features:.....	3
Changes of MIB & D-View Module:.....	3
Problems Fixed:	3
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
2.02rc019	2014/12/22	DAP-2310	B1
2.06rc029	2015/07/06		

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

The screenshot shows the D-Link Web-UI interface for a DAP-2310 device. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2310, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

System Information	
Model Name	DAP-2310
Firmware Version	2.07 15:17:46 03/15/2016
System Name	D-Link DAP-2310
Location	
System Time	03/23/2016 14:27:54
Up Time	0 Days, 00:6:20
Operation Mode	Access Point
MAC Address	c4:a8:1d:91:b1:10
SSID 1~7	c4:a8:1d:91:b1:11 ~ c4:a8:1d:91:b1:17
IP Address	192.168.0.205

New Features:

None

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V2.07	1. Fixed security issue of web server is vulnerable to buffer overflow while parsing the cookie.

Known Issues:

Firmware Version	Known Issues
V2.07	None

Related Documentation:

- DAP-2310 User Manual v2.04