



Firmware Version: 1.01r038

Published Date: 2020/Oct/20

Content:

Upgrading Instructions: 2
 Upgrading by using Web-UI..... 2

New Features: 2

Changes of MIB & D-View Module: 2

Problems Fixed: 3

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.00r013	2019/Nov/29	DAP-3666	A1
1.01r038	2020/Oct/20	DAP-3666	A1


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter <http://dap3666.local> to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
3. Enter administrator's username and password, user name and password is "admin" by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. None

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
1.01r038	<ol style="list-style-type: none"> 1. Layer 3 discover fail when cross NAT with Source Port changes. 2. Domain Name only use 21 character when set by DNC. 3. Disassociate all STA when AP boarding. 4. Some Android phone cannot pop up login page. 5. Disable Wi-Fi when AP is unmanaged. 6. Unable to modify Subnet mask on AP. 7. Configure some Hotspot 2.0 parameters will cause AP to reboot. 8. AP send STA disconnection log twice. 9. Modify Bandsteering parameter, so device will not panic when many clients connect/disconnect within a short period of time. 10. External passcode authentication fails. 11. Add watchdog mechanism to fix unstable issue. 12. In some condition AP will reboot automatically. 13. Correct system date settings. 14. In some condition Passcode authentication need to re-login again when roaming. 15. RADIO (re)initialize on both RADIO bands randomly 16. In some condition, AP will freeze or crash after few days.

Known Issues:

Firmware Version	Known Issues
1.01r038	<ol style="list-style-type: none"> 1. When DAP-3666 is configured in wireless client mode, the client connected to the DUT cannot obtain an IP address. (Only happens on some model of uplink AP) 2. DAP-2662/3666 will feedback other VLAN IP to DNC-100 for local IP address. 3 WPA only and TKIP will disable in WDS/WDS with AP/AP Client mode 4. Sometimes incorrect AP IP showed at DNC>Monitor> Access Point 5. In few condition, auto channel optimization will be abnormal (Managed by DNC-100)

Related Documentation:

None