DBA-3620P A1 Firmware Release Notes





Firmware Version: 2.00.001 Boot Code Version: 1.00 Nuclias Portal Version: 2.1.2.5

Published: Apr. 20, 2020

These release notes include important information about D-Link Nuclias Access Point firmware revisions. Please verify that these release notes are correct for your Access Point:

Content:

Revision History and System Requirement:	2
Upgrade Instructions:	2
New Features:	2
Changes of Command Line Interface:	2
Problem Fixed:	3
Known Issues:	3
Related Documentation:	





Revision History and System Requirement:

Firmware Version	Date	IMOGAL	Hardware Version	Remark
V2.00.001	20-Apr2020	DBA-3620P	A1	1st release

Upgrade Instructions:

When the device added to Nuclias portal, the Nuclias portal will automatically update the Access Point firmware to the latest version. User can go to SETTINGS→Firmware → ACCESS POINT UPGRADE to change the firmware upgrade policy and there are three options:



New Features:

Firmware Version	New Features
V2.00.001	First release

Changes of Command Line Interface:

The section below only shows command line changes that may bring backward compatibility issues with configuration settings for previous version of firmware.

Any new feature commands that do not have backward compatibility issues are not included in the below section.







DBA-3620P A1 Firmware Release Notes

V2.00.001	First Release

Problem Fixed:

Firmware Version	Problems Fixed
V2.00.001	First Release

^{*} D-Link tracking number is enclosed in ()

Known Issues:

Firmware Version	Issues	Workaround

Related Documentation:

- DBA-3620P A1 User Manual V1.0
- DBA-3620P A1 QIG V1.0
- Nuclias user manual

