



FW Version: 4.7.5.1

Published Date: 2021-11-01

Copyright © 2021

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

D-Link

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content:

REVISION HISTORY AND SYSTEM REQUIREMENT:	2
NOTES FOR CONFIGURATION AUTO-BACKUP/RESTORE IN USB STORAGE:	
UPGRADING INSTRUCTIONS:	.3
NEW FEATURES:	.3
PROBLEMS FIXED:	. 5
KNOWN ISSUES:	14
RELATED DOCUMENTATION:	16



Revision History and System Requirement:

Firmware Version	Date	Model Hardware	History
4.7.6.1	11 Nov 2021	DWC-2000/Ax	1. New features and bug fixes
4.7.5.1	01 Feb 2021	DWC-2000/Ax	1. New features and bug fixes
4.7.4.2	29 May 2020	DWC-2000/Ax	 Support DWL-X8630AP, DWL-8720AP, DWL-6720AP New features and bug fixes
4.7.2.1	16 Apr 2019	DWC-2000/Ax	2. New features
4.7.1.1	18 Dec 2018	DWC-2000/Ax	1. Support DWL-8620AP
4.7.0.3	02 May 2018	DWC-2000/Ax	 Support new APs Captive portal optimization Improving stability of controller GUI access (LSH project critical error issue)
4.6.0.2	20 Nov 2017	DWC-2000/Ax	Support new AP Bug fixes and enhancement Update v4502 Problem fixed item.
4.5.0.2	08 Dec 2016	DWC-2000/A1	Bug fixes and enhancement
4.4.0.3	20 May 2015	DWC-2000/A1	Bug fixes and enhancement

Firmware Details:

dlink green

Image Version	HW	MD5 Checksum
DWC-2000_Ax_FW4.7.6.1_WW	Ax	936cbf9337fa052b0a50d3280234e61a

Notes for Configuration Auto-Backup/Restore in USB Storage:

D-Link DWC Unified Controller support configuration backup or restore automatically while a USB drive is inserted. Following information instructs what condition will perform backup/restore.

1. The configuration will be automatically backed up to the USB drive as soon as the USB drive

D-Link

is inserted. The back name has format <Model Name>_<Serial Number>.cfg provided this USB drive doesn't have a backup configuration file from a DWC already present.

- 2. The system LED on the DWC blinks 3X in amber to indicate a backup operation has started.
- 3. The configuration in the USB drive can be updated if the user manually clicks 'Save Settings' in any GUI page and provided the Model Number and the Serial Number of the DWC matches with the file already present in the USB drive.
- 4. In case of reboot, the DWC checks for the presence of configuration file (with format ModelName_SerialNumber.cfg). If found, the configuration from the USB drive is restored on the DWC. If a configuration file with the correct format is present in both connected USB drives, the configuration from the first USB drive will be used to restore the DWC.
- 5. The USB drive can have only one configuration with the above mentioned format for each model name.
- 6. If the USB drive is plugged in to the DWC which is in factory default state, then during reboot, no backup is taken since no custom configuration file exists in the DWC by that time. The custom configuration is stored on the USB drive once the user clicks Save Settings in any GUI page.

Upgrading Instructions:

Upgrading by using Web-UI

For detailed installation and upgrade instructions, please refer to the Firmware Upgrades chapter in the *DWC-2000 User Manual ver. 1.00.*

New Features:

Firmwa re Version	New Features
4.7.6.1	1. AP Network configuration UI Enhancements & AP LED management support
	1. Changeable Captive Portal IP
	2. Schedule reboot
4.7.5.1	3. Application Overview (only works with DWL-6620/7620/8620/6720/8720AP)
4.7.5.1	4. Scheduler per SSID (only works with
	DWL-6620/7620/8620/6720/8720/X8630AP)
	5. Fast roaming (only works with DWL-6620/7620/8620/6720/8720AP/X8630AP)
	1. Support DWL-X8630AP, DWL-8720AP, DWL-6720AP
4.7.4.2	2. SLA enhancement
	3. SLA Option for CP Permanent User



4. Users per captive portal group: DWC-2000/500, DWC-1000C1/250 & Users
generated per billing profile: DWC-2000/1024, DWC-1000C1/512
5. AP Grouping
6. Delete expired users SPR# 64972 (To add manually delete option on GUI)
7. GUI display enhancement
8. Local MAC DB enhancement, Local MAC Auth DB grouping and MAC address
masking, Password for MAC Auth
9. Forced Login option and Multi Login number limit
10. CP Sessions page refinement (SPR #65334)
11. Replacing MD5 hash with SHA512 for Authorize.net users
12. Default Password change
 Social login for Google, Line & Weibo (SNR v1.06)*
 Need to add support for Maximum clients limit per SSID*
Note: New features (*) need changes on AP, it's not supported on all DWL AP forma
releases yet, only work with test releases as below.
a. DWL-6600AP/3600AP: upgrade_4_2_0_15B003C.tar
Link: https://www.dropbox.com/s/kn2bh17utfrck8k/upgrade 4 2 0 15B003C.tar?
<u>dI=0</u>
Md5sum: fc5ac52342197123d01621667d53e962
b. DWL-8610AP: DWL-8610_FW_v_4.3.0.10B022C.tar
Link: <u>https://www.dropbox.com/s/h1rcqukb59ej44g/DWL-8610 FW v 4.3.0.10B0</u>
$\frac{22C.tar?dl=0}{2}$
md5sum: 956661cb567e1b392a4dfe65445e0206
=======================================
 WPA3 setup options on DWC (for DWL-X620AP)**
 Add LAG and LACP options (for DWL-X620AP)**
DI20190729000005 DJP DWC-2000 There is no WMF setting in the wireless
profile (for DWL-X620AP)**
Note: New features (**) need changes on AP, it's not supported on all DWL AP forma
releases yet, only work with releases as below.
DWL-8620AP/7620AP/6620APS: v4729 and onwards.
1. MAC-Bypass*
2. FB WiFi enhancement*
4.7.2.1 3. Default NTP Server proposal (adding tertiary server)
4. GUI enhancements
5. UAP Direct Config (for managed AP)*
6. Navigator
dlinkigreen



	Note: New features (*) need changes on AP, it's not supported on all DWL AP formal			
	releases yet, only work with test releases as below.			
	a. DWL-6600AP/3600AP: upgrade_4_2_0_15B003C.tar			
	b. DWL-8610AP: DWL-8610_FW_v_4.3.0.10B019C.tar			
4.7.1.1	Support DWL-8620AP			
4.7.0.3	Support DWL-6620APS and DWL-7620AP			
	1. Support 3610AP/6610AP_B1			
	2. Human Readable Log for AP Lost Management			
	3. Sync MAC authentication and CP attribute with DWS			
4.6.0.2	4. Dynamic language packs support			
4.0.0.2	5. Facebook Wi-Fi support			
	6. Firmware naming change to Ax			
	7. Restricting A2 HW to downgrade any firmware $< v4602$			
	(Cut-in Rev A2 due to EOL of eMMC, and v4602 supports new eMMC)			
	1. DWL-8710AP Support			
4.5.0.2	2. Multiple LDAP SSID Mapping Enhancement			
	3. Hotspot enhancement changes			
	4. AP firmware upgrade enhancement.			
	5. New Dashboard and Wizard feature set.			

Problems Fixed:

Firmware Version	Problems Fixed
	1. secondary 802.11a/n/ac auto eligible channel are showing empty (DBG21011038)
	2. some issue on DWC-2000's web GUI.[DI20210922000009-Japan]
	HQ2-0210923000010
	3. Country Code - CUBA unable to set (HQ20200213000011)
	4. Unable to receive "Multicast to Unicast", "DHCP Offer/ ACK to Unicast" and "Band
4761	Steering" configuration in peer controller when pushed from cluster controller.
4.7.6.1	(HQ20201113000007)
	5. The number of managed APs on master controller is inconsistent between managed AP
	page and header menu. (HQ20201113000007)
	6. AP schedule time monitor (HQ20210113000009)
	7. Application Overview not working[DI20210219000001-Australia] HQ20210225000005
	8. Unable to disable WPA/TKIP when SSID set to Enterprise[DI20210311000002-Australia]
reen	



dlink

	HQ20210311000009
	9. DWC-2000 + DWL-7620 - issue with AP Profile[DEUR20210217000003-Central Europe]
	HQ20210312000001
	10. Modifications to DTIM, WPA-TKIP and Fast Roam in AP Profile and Radio Pages
	HQ20210324000006
	11. POP-UP Message information is not showing proper information when we perform
	firmware upgrade from GUI. HQ20210408000001
	12. WLAN scheduler - Syslog wrong time[DEUR20210608000004-Central Europe]
	HQ20210610000014
	13. CPU Utilization is more than 80%[DI20210706000004-Australia HQ20210706000010
	14. doesn't allow to change 'MAC Authentication' to Disable.[DI20210728000003-Japan] HQ20210729000002
	15. Able to add more than 128 entries in 'Block Client' page. HQ20210830000004
	16. DWC/DWL - AP Profile QoS Configuration
	17. Hide "Link Aggregation "on DWL-X720AP
	18. Emoji WiFi Names
	19. WLAN Visualization – Disable
	20. Mechanism to avoid unsupported HW models being configured with WPA3, VAP
	Scheduler and Fast BSS Transition.
	21 Disable APSD mode by default
	22 AP List Enhancement and LED off
	23 Show Schedule reboot options but not allow to configure in peer
	24 AP Radio Profiles - Primary and Secondary Load balancing field should be in sync
	25 incorrect CP login page for Permanent user when we are trying to access https sites.
	26 Observed the Bad parameter Error message when we configure the SSID from the Navigator.
	27. Enhancement to support 36 chars for AP Firmware file name.
	28. Schedule Reboot Enhancement in cluster-peer support
	29. Observed Critical Error message when we manage bulk number of AP's.
	1. Problem with FW upgrade and config.
	DRU20190628000001/ HQ20190702000006. SPR #66650
	2. LOGO of the captive portal billing profile
	[DEUR20200826000001-South Europe] HQ20200901000008/ SPR #68887
4.7.5.1	3. Issue with CP
	[DEUR20200924000004-South Europe] HQ20200928000010/ SPR #69089
	4. [DWL-8600AP/DWC-2000] CH 140 issue. HQ20201029000002/ SPR #69403
	5. After reaching 125 managed APs, the Managed page can not be displayed any
	more - A critical error encountered while loading web page
reen	



		[DEUR20201104000005-Eastern Europe] HQ20201105000011/ SPR #66915
		6. Multiple issues with the Controller & AP setup
		[IMA20201028000003-India] HQ20201113000007/ SPR #69445
		1. RADIUS server setup issue. DBG18061014
		2. In trunk mode, vlan-1(default vlan-1) should get tagged like other VLANs
		3. Upgrade the dhcpv6 server code HQ20181115000003 / SPR #64995
		4. [Web GUI] AC Client is counted as both 802.11N &802.11AC client
		HQ20190114000006/ SPR #65355
		5. Neighbor AP entries are not showing for 2.4Ghz radio in Neighbor AP status
		page. SPR #65482
		6. DWC-2000 WEP can be set even if 11n or 11ac is enabled on 5GHz
		DI20190214000003/ HQ20190215000007. SPR #55940
		7. DWC-2000 Does not send Email logs for Managed AP Status.
		DI20190222000001/ HQ20190225000002/SPR #65715
		8. DWC-2000 Sending Radius packets to Primary -> Tertiary -> Secondary
		Server. DI20190221000003/ HQ20190305000023/ SPR #65815
		9. Unable to upgrade DWL7620Ap from Managed AP page. SPR #65849"
		10. IP sorting columns is incorrect in Managed APs ane AP Provisioning page.
		DEUR20190320000004/ HQ20190322000010 SPR #65894
		11. Removing debug logs. HQ20190510000007/ SPR #66176
	4.7.4.2	12. Critical error page appears when access into ""Event"" page with customer's
		configuration. DI20190527000001/ SPR #66242
		13. Popup window cannot be closed by close button. HQ20190523000001/ SPR
		#66246
		14. Wrong information of Radar Status in Radio Details/ DWL-8610AP.
		HQ20190516000012
		15. Cannot add 2048 MAC addresses to Local MAC authentication database.
		HQ20190604000012/ SPR #66294
		16. DWL-7620AP, Auto channel doesn't work on 2nd 5G. DI20190315000003 SPR
		#66613.
		17. Radio details are not showing properly in the Managed AP List page when we
		manage more number of APs. DEUR20190827000006/ HQ20190904000009 SPR
		#66785
		18. Critical error appear in managed AP
1112		DEUR20190826000003/HQ20190828000006, SPR #66915
		19. No option for Channel and Power for 3rd radio
		DUSA20191031000001/ HQ20191101000003, SPR #66528
		20. Fix: SSL/TLS Weak Cipher Algorithm (OnSec-TC-03003001)
dlinkigr	een	



	1	N
		21. Internal DHCP server issue. DRU20191225000003/DWC-2000. SPR#67408
		22. DWC-2000 GUI display, to add 200/500 to the drop-down list SPR# 66954
		23. No CLI command for radius accounting configuration. DGC20200225000001.
		SPR# 67763
		24. Web GUI Management feature is not blocking CP login users from accessing
		controller Web GUI. DEUR20200220000004. SPR# 67834
		1. DWL-XX10APs are crashing in loop when they are getting managed with
		latest DWC-1000C1 release v4.7.2.1. (DBG19020237) SPR #65544
		2. Observed error on viewing billing profiles from CLI (DBG17020231). SPR
		#60641
		3. [DLAB] Observed some issue with snmpwalk commands and in MIB
		browser. SPR #61032
		4. Facebook WiFi Enhancement (SNR v1.06). SPR #62604
		5. DWC-1000 - issues with visualization Win10 64bit.
		(DEUR20180228000006/ HQ20180305000016). SPR #63462
		6. NTP Server Enhancements (adding tertiary server)
		(DEUR20170516000006/ HQ20170517000003). SPR #64200
		7. Add ATF feature support for DWL-6620/7620AP profile types and with
		profile type 'Any' in DWC. SPR #64207
		8. Observed ipset related logs in DLI and shell needs to be suppressed.
		(DBG18070008). SPR #64239
	4 7 9 4	9. Multi Radius support & Profile selection for Mac authentication in AP
	4.7.2.1	profile SSID page. SPR #64296
		10. Issue with DST and SNTP (DWC-1000/C1) (DEUR20180620000002/
		HQ20180626000010). SPR #64325
		11. Japan 5G channel issue for managed 7620AP (DI20180704000002/
		HQ2018071000005)
		a. Able to configure same channel in both radio mode primary and secondary
		in default and custom AP Profile while managing 7620AP. And notification
		enhancement when configure primary 5Ghz and secondary interface. SPR
		#63530
		b. Channel # 100 not shown in the secondary radio issue. SPR# 64414
		12. Certification revoked in Wlan Visualization (HQ20180917000003). SPR
		#64430
		13. DWC cannot manage DWL-6700 when the hardware type of AP profile is
		DWL-6700 (HQ20180809000014). SPR #64507
		14. Device is not allowing to enable "Radio Resource Management" and
		"Space time block code" options in radio settings of DWL-6610AP(A1)
dlink	een	
uninkign	een	



	4. Cannot remove DNS Hostname Mapping via either the GUI or CLI interface
	only) SPR #52908
	reboot. (DEUR20170111000006/ HQ20170113000006) (DWC-1000/A1/B1
	3. The problematic AP profile gives wrong SSID assignment after system
4.7.0.3	and WPA2/-Enterprise)
	included for Captive Portal authentication. (Works fine for MAC authentication
	2. RADIUS attributes (Calling-Station-Id and Called-Station-Id) are not
	(DEUR20170131000013/ HQ20170202000026). SPR #59620
	1. Wrong display of Expiration Date and Time on Frontdesk page.
	(DEUR20180718000001/ HQ20180719000005) SPR #64364
	8. Can't upload firmware to AP DWL-6610AP/B1
	RADIUS profile (DBG18061026, DBG18061007). SPR #64257
	7. Cannot edit RADIUS profile via CLI when reach Max Radio server and
	6. Logout button doesn't work (DBG18060979). SPR #64256
	CSV file (HQ20180409000019). SPR #63736
	5. Maximum limit for Per group ADMIN/GUEST/FD reached Error while upload
4.7.1.1	HQ20180117000002). SPR #63169
	4. Missing TLS option in Remote Logs section. (DUSA20180117000001/
	HQ20180427000006). SPR #63940
	3. The issue with removing users (DRU20180426000002/
	HQ20180522000006). SPR #63945
	2. Guest account vulnerability by SSH (DRU20180521000002/
	HQ20180423000005). SPR #63862
	1. Failure when building controller cluster (DEUR20180420000006/
	#65013 (DWC-2000 only)
	19. CLI command issue (DEUR20181123000003/ HQ20181126000003) SPR
	(DI20181019000001/ HQ20181019000004) SPR #64866 (DWC-2000 only)
	18. Unable to access webUI from port 1 when Voice VLAN option is activated
	only)
	maximum size of 2048 KB (HQ20170303000010) SPR #64769 (DWC-2000
	17. WLAN visualization background images upload limit should be 12 with
	RADIUS accounting for roaming clients [SNR 1.04]
	(DEUR20170403000007/ HQ20170420000017). SPR #64583
	16. Radius Accounting sends wrong info if client is roaming
	(OID: 1.3.6.1.4.1.171.10.121.1.2.5.9.1.1). SPR #64528
	15. Need to add support for SNMP OID to get cpu usage in dwc-1000 series
1	







dlinkigreen

22. DWL-6610APE management issue. Not allow WPA2+TKIP setup
(DEUR20171222000001/ HQ20171227000004) SPR #62995
23. DHQ CP Login issue (General fixes/optimizations and LDAP Auth flow
changes)
24. LSH project critical error issue, system pop-up error msg when accessing
GUI page "A critical error encountered while web page", a reboot needed
to have it back (HQ20180125000010) SPR #63234
25. LAG issue (Link Aggregation static mode) with DGS-3420
(DI20171006000001/ HQ20171006000013) SPR #62539
26. Configure default route on CLI (DEUR20171027000004/
HQ20171027000010) (DWC-1000 C1 only) SPR #62631
27. Config backup/restore via DV7 issue (DI20171012000001/
HQ20171013000009) SPR #63406
28. DWC-1000 config issue with update (from 4.4.1.3B201C_B1_WW to
4.6.1.1), (DEUR20171123000005/ HQ20171124000005) SPR #62776
29. DWC-2000 the expired temporary users within DB are not automatically
deleted. (DEUR20171109000003/ HQ20171110000004) SPR #62720
30. To have TLS on/off (Maintenance»Logs Settings»Remote Logs) for
DWC-1000 A1/B1/C1 only, (DUSA20180117000001/
HQ20180117000002) SPR# 63169"
31. Adding the warning message whenever a reset to factory default is needed
during firmware downgrade process. (DI20180119000003/
HQ20180131000007) SPR# 63265
32. Lost configuration after downgrade firmware. (DI20180119000003/
HQ20180214000007) SPR #63351
33. WLAN Visualization image issue, the uploaded file size is zero.
(DEUR20180228000006/ HQ20180305000016) SPR# 63462
34. WLAN clients can directly access the Internet without being redirected to
the Captive Portal (DEUR20180305000004/ HQ20180307000009) (fix for
DWC-1000/C1 only) SPR# 63498
35. DBG17030351 TCP SYN scan, closed port should not be detected
 (DWC-2000 v4602)
36. DBG17030352 UDP port scan, no ports should respond to UDP port scan.
(DWC-2000 v4602)
37. DBG17040046 TCP-FIN scan, no ports should respond to TCP-FIN scan.
(DWC-2000 v4602)
38. POP3 authentication server should accept the FQDN name with more than
15 characters. (DI20170320000001/ HQ20170320000005) SPR #60276



		39. DWC-1000 - WLAN Wizard only supports A/B/G/N not AC
		(DEUR20170127000002/ HQ20170202000013) SPR #59495
		40. Incorrect warning message in peer device when try to start manual power
		adjustment. (DI20170228000003/ HQ20170301000025) SPR #60210
		41. DWL-6700AP status is not changing to standalone from managed mode.
		(HQ20170517000004) SPR #60943
		42. In customized captive portal page, the login successful page shows
		Password Change option wrongly, it shouldn't be available since it was
		disabled. (DEUR20170717000004/ HQ20170718000008) SPR #63334
		1. DWC-2000_WDS_Incorrect WDS status info for the WDS link between two
		DWL-8610AP [continuous case from DBG16090029] DBG16090122
		2. Captive Portal issues from DHQ setup HQ20160627000021
		3. Unable to add 625 users from CSV only 624 are added DBG16110376
		 LAN client cannot access Internet when default gateway is DWC HQ20160831000011
		5. httpd upgrade, Idap changes & logging changes for issues observed in
		customer setup HQ20160822000012
		6. Need to allow space character in SSID profile configuration from both SSID
		profiles and ap profile SSID pages HQ20161220000011
		7. [DLAB] Unable to get the value for OID "wsManagedAPRadioBandwidth"
		when radio bandwidth is 80 MHz HQ20160722000011
		8. Unable to disassociate clients from SNMP browser with OID
		"wsAssociatedClientDisassocaiteAction" HQ20160705000002
	4.6.0.2	9. SLA content is not coming properly in mobile phone HQ20160831000014 10. QoS issues in DWC GUI pages HQ20160707000003
		11. Validation checks for importing invalid files mac authentication in wizard
		dashboard DBG16080297
		12. Incorrect error message when we add 65th AP profile DBG16080306
		13. User DB invalid csv file import issues DBG16080158
		14. DWC-2000_webUI_DWC show the incorrect info in QoS page when Radio
		is off DBG16090024
		15. [DLAB] Unable to manage APs from 34 to 64th AP profiles when max AP
		profiles are configured in the device
		16. [DLAB]unable to configure IP ACL rule with IP address of last octet '0' 17. [WebGUI] Status Bar shows Operation Failed When we edit & save SSID
		HQ20160621000015
		18. Authorzie.net error mapping if any issue in configuration of billing profiles
		HQ20160825000010
		11620100052000010
dlinkigr	een	



I		
		19. When added an ACL rule with L4 port http then when edit it is showing as
		www DBG16110379, HQ20161116000010
		1. Unable to delete/deactivate the licenses through CLI HQ20130426000004
		2. OpenSSL Vulnerability Change Cipher
		3. Device is vulnerable to SQL injection attack for cookie.
		4. Not able to perform trace route or ping functionality of ipV6 addresses
		from diagnostics page HQ20141104000020
		5. Need enable 80Mhz for Mexico
		6. WLAN IP address display 10.90.90.90
		7. Observed critical error after STA pass captive portal Login in IE11
		browser(DWC-1000) HQ20150204000014
		8. Unable to open the GUI/frontdesk page of DWC-2000 device when it is
		connected to DSR device in NAT mode HQ20150324000017
		9. Observed critical error in the IE 11 browser when user refreshes CP
		window.
		10. Eliminate the double quote for WPA/WPA2 key in the "print ticket" of
		DWC-1000 device HQ20150518000017
		11. Observed critical error in discovered ap page when we add large ip range
		HQ20150804000021
		12. WEP security mode is not persisting after reboot for the default vap
	4.5.0.2	ssid's in dwc-2k
		13. Upper level channels are not displaying in 5GHz radio for all countries.
		14. When changing the radio Primary Channel from lower to upper then
		bandwidth is also getting effected from 40 to 20 HQ20150907000008
		15. IN CLI and in status dashboard memory utilization values should have
		unit MB not KB HQ20150930000015
		16. Enable redirect functionality not working on mobile devices when CP
		type as SLA HQ20151006000015
		17. DWC-2000: Device is vulnerable to CSRF attack.
		18. Channels list in managed ap page, in status managed ap page channel
		list pages are different from ap profile radio page HQ20150701000015
-		19. User is able to add the ip address in the DHCP pool which is alredy
		configured in the DHCP reserved IP page HQ20150810000022
		20. license activation page is not working in Localization branch
		21. Able to save diff serv policy with diff serv class which doesn't have a
		match selector HQ20141110000017
		22. Need to apply the patch for Multiple Vulnerabilities#CVE-2015-3195
		23. Wireless configuration is not persisting some time
dlinkigre	een	

24. Unable to open DWC-1000 GUI pages when device is behind NAT with
Port forwarding Rule HQ20151221000015
25. Force roaming option is getting disabled after reboot for managed ap
entry added in valid access points page HQ20160106000002
26. Static key is being used for SSH Communication.
27. critical error in managed ap page HQ20151216000013
28. Ignore Broadcast option need to be removed from cli for ssid
configuration
29. When both the radio of peermanaged ap is off then channel is not
getting updated in master HQ20160201000019
30. Need to add test build patch for the "High CPU utilization issue"
31. Observed 500 Internal Server error with customer configuration file
HQ20160127000016
32. Able to configure CP type [SLA/Permanent/Temporary] for the Control
VLAN from CLI HQ20160201000014
33. Spelling mistake in pay pal configuration page. HQ20160218000017
34. LAN related logs are not coming in DWC-2000 HQ20160126000017
35. Need to add port 443 for remote management and ssl vpn
36. SSL/TLS use of weak RC4 cipher-CVE-2013-2566
37. DWC-2000 M2 : Increase the MAC Auth database limit to 2048
38. Cavium glibc "Skeleton Key" Vulnerability Notification – CVE 2015-7547
39. The managed APs location information will be incorrectly overwritten.
DBG14070102
[DWC] WDS link status and statistics pages are showing incorrect radio modes
for the WDS connection in DWC-2000 DBG15100075

Tracking Issues:

Firmware Version	Tracking Issues (The potential fix has not been confirmed by customer or OBU)
N/A	N/A

Known Issues:

Firmware Version	Known Issues	



	IP ACL functionality is not working in DWL-6620APS & DWL-7620AP and
	DWL8620AP.
	MAC ACL functionality is not working in DWL-6620APS and DWL7620AP and
	DWL8620 AP as options are not available in AP
	Captive portal temporary user forced login & multi-login for custom CP profile is not
	working
4.7.6.1	MAC based vlan functionality is not working for DWC2000.
4.7.0.1	The SLA terms and conditions after redirect the Captive portal page & After
	generating the billing user not showing the same and also user able to login CP
	session without clicking the terms and conditions option after generating the billing
	users.
	Observed that "Neighboring AP's" information is not seen in controller when
	managed AP is DWL-6700 AP.
	DBG19030516 DWC-2000_4.7.2.1_cannot restore config via USB (Failed
	with NTFS, but works with FAT32) (SPR #65875)
	DBG19030417 DWC-2000_4.7.2.1, wlan visualization failed, managed-AP
	did not save after reboot (SPR #65862)
4.7.5.1	DBG21011038- Auto Eligible Channels of Secondary 802.11a/n/ac is empty
	after factory reset the DUT.
	DBG21011072- The operational status of the DWL-6610AP's SSID always
	shows 'DOWN' in VAP detail page on DWC-2000.
	DBG19030516 DWC-2000_4.7.2.1_cannot restore config via USB (Failed
4.7.4.2	with NTFS, but works with FAT32) (SPR #65875)
4.7.4.2	DBG19030417 DWC-2000_4.7.2.1, wlan visualization failed, managed-AP
	did not save after reboot (SPR #65862)
	DBG17030308 Security scan - http access with the Password in plain-text
	DBG19030516 DWC-2000_4.7.2.1_cannot restore config via USB (Failed
	with NTFS, but works with FAT32) (SPR #65875)
	DBG19030417 DWC-2000_4.7.2.1, wlan visualization failed, managed-AP
	did not save after reboot (SPR #65862)
4.7.2.1	DBG19030585 DWC-2000_AX_4721_After user connect the WLAN client
	and purchase the Billing user on-line via authorize.net, it will not redirect to
	the user detail and not show "Email and Login Now" button. (Needs
	replacing MD5 hash with SHA512 for Authorize.net users)
	DBG19030503 Need to add 5GHz DFS channel list in the DWL-X620AP radio
	profile with country code which support 5GHz DFS channel (SPR #65885)





	DBG19030506 The function "Detected Clients Delete" should be enable by
	default. But in the document the description is "By default it is disabled."
	(SPR#65394)
	DBG19030494 DWC-2000 not support the ".bin" file to upgrade the
	DWL-7620AP's firmware in Managed APs list page. (SPR #65849)
4.7.1.1	DBG18080275 When the user tries to change channel from AP Profile Radio page, it is not working with DWL-8620AP in this use-case. SPR #64459
4.7.0.3	N/A
	DBG17030308 Security scan - http access with the Password in plain-text DBG17030351 Security scan - TCP Syn scan fail
	DBG17030352 Security scan - UDP port scan fail
4.6.0.2	DBG17040046 DWC-2000 response the TCP-FIN this kind of probe packet
4.0.0.2	for all listening ports.
	DBG17030332 Client is not able to redirect properly due to
	m.facebook.com is imposing HSTS mechanism
	DBG16120072-Cannot form cluster after uploading the customer's
	settings.
	DBG16120077-The WiFi-channel won't follow what we set in the controller.
	DBG16120024-DWC-2000_CLI_Vlan setup via CLI not work
4.5.0.2	DBG16110379-DWC-2000_IP-ACL_The service of the IP-ACL issue
	DBG16110376-Cannot add user through CSV
	DBG16110307-The incorrect WEB UI of DWC-2000
	DBG16110292-difference in alert message usage and actual usage left for
	temp CP

Related Documentation:

- DWC-2000 User Manual ver.1.00
- DWC-2000 CLI Reference Guide ver. 1.00

