



Firmware Version: V4.5.0.1
Published: May 12, 2016

Content:

Revision History and System Requirement:.....2

New Features:2

Problems Fixed:2

Known Issues:2

Related Documentation:.....2

Revision History and System Requirement:

FW Version	Date	Model	HW	MD5 CHECKSUM
V4.5.0.1	12-May-2016	DWL-8710AP	A1	9d24906109a74baac0f2391760a0697d

New Features:

Firmware Version	New Features
4.5.0.1	N/A
4.5.0.0	<ol style="list-style-type: none"> Initial release Recommend controller/firmware version: <ul style="list-style-type: none"> DWC-2000 FW v4.4.0.3B601C or above DWC-1000 FW v4.4.1.2B501C or above DWS-4026 FW v4.3.0.3B028 or above Root Access should be denied for admin CLI user to counter moose vulnerability

Problems Fixed:

Firmware Version	Problems Fixed
4.5.0.1	LED issue
4.5.0.0	Initial release

Known Issues:

Firmware Version	Issues
4.5.0.1	N/A

Related Documentation:

- DWS-x600AP Series Manual
- DWS-x600AP Series CLI Manual