



Firmware Version: 1.25r053
Published Date: 2025/04/24

Content:

Upgrading Instructions: 2

 Upgrading by using Web-UI..... 2

New Features:..... 3

Changes of MIB & D-View Module: 3

Problems Fixed: 3

Known Issues: 4

Related Documentation: 4

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00r007	2021/06/18	DAP-X2810	A1
V1.10r015	2022/03/18		
V1.20r033	2023/02/21		

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Please also

1. Make sure your DAP-X2810 has to manually assign a valid static IPv4 address or get a valid IPv4 address from DHCP server before upgrade FW.
2. Do not power off your DAP-X2810 when FW upgrading.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter <http://dapx2810.local> to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
3. Enter administrator's username and password, user name and password are "admin" by default.
To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

New Features:

1. support SNMPv3 feature
2. Support Captive portal's new features : External Captive Portal/Mac Address/Social Login (Walled Garden)/Click through
3. Support PayPal
4. Support Auto RF Optimization
5. VueJS V3.0 replace Angular JS for Web pages
6. KR Country domain 5GHz should support 165.
7. SG Country domain 5GHz should support 100,104,108,112,132,136,140.

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V1.25	1. Fix [DI20240530000007] According to the manual WebUI should hold up to 500 logs, but more than 500 logs on WebUI 2. Fix [DI20240530000007] CLI get syslog information is different from WebUI View Log 3. Fix [IMA20230624000001] AP Offline Issue 4. Fix [DGC20230511000001] Ipv6 display issue. 5. Fix [DI20230410000003] KR request for firmware with DFS channel disabled. 6. Fix [DI20230404000001] After upload the DJP's certificate, fail to access HTTPS. 7. Fix [DI20230118000003] WebUI doesn't gray out Auto Channel Selection when AP MAC Address is not empty 8. Fix [DEUR20221214000002] Asymmetric VLAN not working with VID1 9. Fix [DI20240619000003] Accounting Radius Not working normally 10. Fix [DI20241206000001] AP became offline after upload configuration , Use DNH to upgrade 2 APs would get 1 AP failed 11. Fix [DI20231003000002] Blank Host Name when Wireless Client uses Static IP 12. Fix [DI20230921000003] WMM for multi SSID1~7 can be selected Enable or Disable

	13. Fix [DI20240109000006] Vietnam Projects Encounter Wireless issues 14. Fix [DI20240524000006] Untag vlan setting does not return DHCP response for WLAN.
--	--

Known Issues:

Firmware Version	Known Issues
V1.25	

Related Documentation: