



Firmware Version: 1.11rc046

Published Date: 2015/07/8

Content:

Upgrading Instructions:.....	2
Upgrading by using Web-UI.....	2
New Features:.....	3
Changes of MIB & D-View Module:.....	3
Problems Fixed:	3
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.06rc025	2015/01/16	DAP-2660	A1

Upgrade Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

The screenshot shows the D-Link Web-UI interface for a DAP-2660 device. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2660, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

System Information	
Model Name	DAP-2660
Firmware Version	1.11 14:19:45 06/19/2015
System Name	D-Link DAP-2660
Location	
System Time	01/01/1970 19:08:02
Up Time	0 Days, 19:8:3
Operation Mode(2.4GHz)	Access Point
Operation Mode(5GHz)	Access Point
MAC Address(2.4GHz)	70:62:b8:50:d2:60
MAC Address(5GHz)	70:62:b8:50:d2:68
SSID 1~7(5GHz)	70:62:b8:50:d2:69 ~ 70:62:b8:50:d2:6f
IP Address	192.168.0.202

New Features:

Support CWM v1.02

1. Disassociation supported on multi-SSID
2. Support Captive portal customization
3. Support config file upload from CWM

Changes of MIB & D-View Module:

CWM_DAP2660 v1.11-R34

Problems Fixed:

Firmware Version	Problems Fixed
V1.11	<ol style="list-style-type: none"> 1. Fixed issue of client can't access the Internet when Ethernet to WLAN disable 2. Fixed users can't access https sites with IE8/IE11 browsers 3. Fixed daylight saving issue 4. Fixed disconnect issue after wireless clients are connected for few weeks 5. Fixed WLAN statistic page display issue 6. Fixed 5Ghz wireless client can't connect to the Internet via IPv6 7. Modify timezone. 8. Fix captive portal on other SSID(including 5G primary and MSSID) will not work when captive portal on 2.4G primary SSID is not enabled

Known Issues:

Firmware Version	Known Issues
V1.11	None

Related Documentation:

- DAP-2660 User Manual v2.01