



Firmware Version: V1.15
Prom Code Version:
Published Date: 2016/03/31

Content:

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2011/7/19	DCS-3112	A1
V1.10	2012/7/25	DCS-3112	A1
V1.11	2013/6/13	DCS-3112	A1
V1.12	2015/1/19	DCS-3112	A1
V1.13	2015/9/22	DCS-3112	A1
V1.14	2015/10/12	DCS-3112	A1
V1.15	2016/03/31	DCS-3112	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file to your hard drive from the D-Link website.
2. Log-in camera web UI and go to **Maintenance/Firmware** web page upgrade
3. Locate the file (upgraded firmware) on your hard drive by clicking **Choose File**.
4. Click **Upload** to upgrade the firmware on your camera.

New Features:

Fireware Version	New Features
V1.11.01	1. Add SNMP function

Problems Fixed:

Firmware Version	Problems Fixed
V1.11.01	1. Remove "guest" account. 2. RTSP authentication default enable 3. Fixed the security of upnp.
V1.12.00	1. Fixed the security of SSL 3.0. 2. Fixed the security of getting the snapshot without authentication
V1.13.02	1.Fixed the security issue of NTPd issue 2.Fixed the security issue of tunneling RTSP streaming over HTTP 3.Fixed the Cross-Site Scripting(XSS) issue 4.Fixed the Cross-Site Request Forgery (CSFR) issue
V1.14.00	1. Upgrade to new signing keys for fixing Code-Signing Key issue
V1.15.00	1. Enhancement for security issue: a. Support TLS 1.1/1.2. b. CSRF protection default enable and follow DHQ CSRF response rule.. c. Fixed CSRF and Referer issue. d. Cross Site Scripting(XSS) issue.

- | | |
|--|--|
| | <ul style="list-style-type: none">e. Disable SSH connection.2. Fixed snapshot/video recording issue while browse UI in IE11.3. Fixed "Image setup" page can't be shown in Safari.4. Fixed Curl issue -mail server SMTP authentication fail.5. Fixed D-Track #HQ2015102700002 [DEUR20151023000013] New Mail Client in firmware is not RFC 2821 conform.6. Closed unknown hidden TCP port 1010. |
|--|--|

Known Issues:

Firmware Version	Known Issues
	N/A

Related Documentation:

N/A