

Driver Utility Release Note

Date 2011.12.29

Release model: P350Q-D212, P550Q-D212 (DSN-6120, DSN-6420)

Files included: DLink_Storage_Service_Setup-2.0.2-x64-en.msi

DLink_Storage_Service_Setup-2.0.2-x86-en.msi

Build number: 302

Bug fixed:

None

Feature change:

1. Add D-Link VeriSign signature files.

Known issues:

1. MPIO driver is for Fibre Channel models. For iSCSI models, it is the default MPIO driver provided by Windows Server operating systems.
2. We recommend using this utility along with FW 2.1.0.

Companion software:

1. Bootloader for MSD ver. 1.00-RC6 (Build 124)
2. FW 2.1.0