Firmware Version: 2.20.B073

Published Date: Aug. 20, 2021

Copyright © 2021

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
2.20.B073	Aug 20 2021	DBG-2000	A1

Upgrading Instructions:

When the device added to Nuclias portal, the Nuclias portal will automatically update the Business Gateway firmware to the latest version. User can go to SETTINGS ->Firmware -> Model UPGRADE to change the firmware upgrade policy and there are three options:

New Features:

Firmware Version	New Features
2.20.B073	1. The first release

Problem Fixed:

Firmware Version	Problems Fixed

Known Issues:

Firmware Version	Known Issues
2.20B073	1. Captive portal with URL redirection is malfunction when set redirection interval as '0' 2. DBG-2000 info at "Network Device" page is incorrenct when right clicking on IGD ICON to check the properties via UPNP 3. UPnP port mapping list won't be cleared for device disconnect 4. If IPsec site to site manual policy select "any" to "any" for remote and local network, the device will lose cloud managemnt due to the cloud control traffic is sent to remote site. 5. The device will lose cloud management if VRRP select WAN interface but configure IP address to its device WAN IP. 6. SMTP ALG is not supported. 7. IGMP proxy is not supported.

Related Documentation:

- DBG-2000 User Manual v2.20.08
- DBG-2000 A1 Quick Installation Guide 1.00