Firmware Version: 1.01r018

Published Date: 2021/05/18

Content:

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
v1.00r015	2021/02/03	DAP-X2850	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site http://tsd.dlink.com.tw.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter http://dapx2850.local to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
3. Enter administrator's username and password, user name and password are "admin" by default.
   To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

New Features:

1. Update IC power for DCAN shipping

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V1.01	None

Known Issues:

Firmware Version	Known Issues
V1.01	None

Related Documentation: