



Firmware Version: V1.11

Prom Code Version:

Published Date: 2016/01/25

Content:

Upgrading Instructions:	Error! Bookmark not defined.
New Features:	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3





Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2013/07/01	DCS-6915	A1
V1.10	2014/12/01	DCS-6915	A1 & A2
V1.11	2016/01/25	DCS-6915	A1 & A2

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

- 1. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
- 2. Click Browse... and specify the firmware file.
- 3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V1.00	First firmware version
V1.10	IPv6

Problems Fixed:

Firmware Version	Problems Fixed
V1.10	 DBG14060563: Default of RTSP authentication changed to "Digest" DBG14070022: Camera can be found after establish PPPoE by SetupWizard. DBG14070043: Fix Day and night setting issue. HQ20140605000020: Fix the camera to be changed BW mode unexpectedly. HQ20140529000007: Fix the camera to go to unknown preset point occasionally. HQ201407030000002: Fix the camera to rotate unexpectedly when the tilt angle is 90 degrees.
V1.11	1. Change to 2015 version Digital Signature.

Known Issues:

Firmware Version	Known Issues







D	داد	te	A	n	\sim	~ i	ın	no	n	ta:	+i,	n n	
ĸ	21a	ιe	a	u	O	CI	J I A	ne	m	a	LIC	on	1:

N/A

