



**Firmware Version:** v2.00r131

**Published Date:** 2019/09/18

---

### Content:

|                                      |                   |
|--------------------------------------|-------------------|
| Upgrading Instructions: .....        | 2                 |
| Upgrading by using Web-UI.....       | <a href="#">2</a> |
| New Features:.....                   | 3                 |
| Changes of MIB & D-View Module:..... | 3                 |
| Problems Fixed: .....                | 3                 |
| Known Issues: .....                  | 3                 |
| Related Documentation: .....         | 3                 |

## Revision History and System Requirement:

| Firmware Version | Date       | Model    | Hardware Version |
|------------------|------------|----------|------------------|
| v1.20rc075       | 2016/09/14 | DAP-2695 | Ax               |

## Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

### Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**

The screenshot shows the D-Link Web-UI interface for a DAP-2695 device. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2695, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

| System Information     |                           |
|------------------------|---------------------------|
| Model Name             | DAP-2695                  |
| Firmware Version       | v2.00 11:21:58 08/05/2019 |
| System Name            | D-Link DAP-2695           |
| Location               |                           |
| System Time            | 01/01/1970 08:01:41       |
| Up Time                | 0 Days, 00:1:42           |
| Operation Mode(2.4GHz) | Access Point              |
| Operation Mode(5GHz)   | Access Point              |
| MAC Address(2.4GHz)    | 00:26:95:12:84:70         |
| MAC Address(5GHz)      | 00:26:95:12:84:78         |
| IP Address             | 192.168.0.106             |

## New Features:

---

1. Use QCA's WDS
2. Remove AP Array
3. Support Nuclias Connect
4. Support DDPv5/APP
5. Use QCA's Band steering
6. In default settings, the network IP address setting is Dynamic IP
7. Support MDNS
8. Modify Time zone settings
9. Update country selection table
10. Move IP filter settings page from Captive Portal to Filter folder, behind WLAN Partition (AP GUI). IP filter function is independent feature and can work with all non-captive portal authentication.
11. Default admin user name/password is admin/admin
12. Add setup Wizard when first login

## Changes of MIB & D-View Module:

---

None

## Problems Fixed:

---

| Firmware Version | Problems Fixed                                      |
|------------------|---|
| V2.00            | 1. D-track -> Fix wrong RADIUS accounting attribute |

## Known Issues:

---

| Firmware Version | Known Issues |
|------------------|--------------|
| V2.00            | None         |

## Related Documentation:

---

- DAP-2695 User Manual v2.00