

DCS-3410 Firmware Release Note

Version: 1.0.2-patch02-7712

Date: Apr. 12, 2013

SVN Revision: 24276

Problems Resolved:

1. Fix security vulnerability issues from CoreSecurity.
2. Enable RTSP authentication as default.

Version: 1.0.2-patch01-4923

Date: Dec. 23, 2010

SVN Revision: 22378

Problems Resolved:

1. Fixed snapshot FTP couldn't reconnect after disconnect 5 minutes.

Version: 1.0.2-4616

Date: Sep 16, 2010

Enhancements:

1. Add settings for new NTSC/PAL sensor.