


DSC-350 Installation in Windows XP



Before connecting the camera run Setup file from the driver set.



Click on START.



Click on "Continue Anyway"
Windows will start copying files.




Click on OK.

Now connect your camera to the USB port.
Windows will detect new hardware:




Select "Install from a specific location (Advanced)". Click on Next.




Put a tick next to “Include this location in the search” and click on BROWSE.


Open the folder where you have extracted the drivers to (in our example it is C:\Driver\dsc-350\WinXP)

Click on Next.





Click on "Continue Anyway"





Click on Finish.

After a short while a new device will be detected:



Select “Install from a specific location (Advanced). Click on Next.






Put a tick next to “Include this location in the search” and click on BROWSE.

Open the folder where you have extracted the drivers to (in our example it is C:\Driver\dsc-350\WinXP)

Click on Next.



Click on “Continue Anyway”



After that you should be able to see the camera under Control Panel > System > Hardware > Device Manager:

