



Firmware Version: v1.05
Prom Code Version:
Published Date: 2016/01/25

Content:

Upgrading Instructions:..... **Error! Bookmark not defined.**
New Features: 2
Problems Fixed: 2
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V1.00	2014/4/28	DCS-5615	A1
V1.01	2014/4/30	DCS-5615	A1
V1.03	2015/7/21	DCS-5615	A1
V1.04	2015/10/15	DCS-5615	A1
V1.05	2016/01/26	DCS-5615	A1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
2. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V1.00	First released

Problems Fixed:

Firmware Version	Problems Fixed
V1.01	Solve Security hole issue.
V1.03	<ol style="list-style-type: none"> 1. Security holes issues. <ol style="list-style-type: none"> a. RTSP authentication b. Slowloris HTTP DoS c. Password Stored in Web Page d. Open SSL binary transmitting) e. Disable SIP port, FTP port, SSL v3.0. 2. Support Onvif14.06 Profile S. 3. Support user input Dynamic DDNS Server Address. 4. Show HW version and Model name in System overview. 5. Supports simultaneous Pan and Tilt.
V1.04	<ol style="list-style-type: none"> 1. Change to 2015 version Digital Signature. 2. Fix D-Lab bug DBG15070328: Fix the D-View Cam Support Error. 3. Show alert message if User use Chrome v45 and above.
V1.05	<ol style="list-style-type: none"> 1. Change default streaming for Chrome use "MJPEG". 2. Update Windows IE plugin for SHA2 certification. (ActiveX) 3. Security holes issues Fix: <ol style="list-style-type: none"> a. Add CSRF protection b. Change RTSP authorization. c. Fix Brute Force attack

Known Issues:

Firmware Version	Known Issues
------------------	--------------

Related Documentation:

N/A