



Firmware Version: 1.11rc062

Published Date: 2014/01/07

Content:

Upgrading Instructions:..... 2
 Upgrading by using Web-UI..... 2
New Features:..... 3
Changes of MIB & D-View Module:..... 3
Problems Fixed: 3
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.10rc041	2012/08/28	DAP-2360	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification**

The screenshot shows the D-Link Web-UI interface for a DAP-2360 device. The top navigation bar includes Home, Maintenance, Configuration, System, Logout, and Help. The left sidebar shows a tree view with DAP-2360, Basic Settings, Advanced Settings, and Status. The main content area displays the 'System Information' page with the following details:

System Information	
Model Name	DAP-2360
Firmware Version	1.11 12:39:06 11/15/2013
System Name	D-Link DAP-2360
Location	
System Time	01/01/1970 00:11:36
Up Time	0 Days, 00:11:37
Operation Mode	Access Point
MAC Address	c8:d3:a3:20:07:28
SSID 1~7	c8:d3:a3:20:07:29 ~ c8:d3:a3:20:07:2f
IP Address	192.168.0.50

New Features:

1. Update new Wireless driver.
2. Enhance Web security issue,
3. Add TX/RX bytes in client info
4. Support APMII v3.0

Changes of MIB & D-View Module:

1. Add dot11ClientTxBytesCount and dot11ClientRxBytesCount in MIB.

Problems Fixed:

Firmware Version	Problems Fixed
V1.11	<ol style="list-style-type: none"> 1. Fix wireless LED doesn't work normal 2. Fix WPA-PassPhrase should support 64 hex 3. Fix WDS can't connect by the WPA Security 4. Fix Enable Daylight Saving function doesn't work normal 5. Fix ARP Spoofing Prevention can input the Null IP address 6. Fix some AP's band show null in Intrusion when detect 7. Fix can't connect by the WPA-PSK in WDS mode 8. Fix when use Periodical Key Change the authentication will change to none 9. Fix can input invalid string in user limit 10. Fix when set WPA password with 64hex in Multi-SSID fail from AP module 11. Fix when set authentication to WPA-PSK and select autokey then use station to connect, it will show none. 12. Fix password support ASCII when length less than 64 13. Fix the bug about VLan can't be enable

Known Issues:

Firmware Version	Known Issues
V1.11	None

Related Documentation:

- DAP-2360 User Manual v1.10