



**Firmware Version:** V1.20  
**Prom Code Version:**  
**Published Date:** 2013/6/13

## Content:

|                               |   |
|-------------------------------|---|
| Upgrading Instructions: ..... | 2 |
| New Features: .....           | 2 |
| Problems Fixed: .....         | 2 |
| Known Issues: .....           | 2 |
| Related Documentation: .....  | 3 |

**Revision History and System Requirement:**

| Firmware Version | Date       | Model    | Hardware Version |
|------------------|------------|----------|------------------|
| V1.00            | 2011/7/19  | DCS-2210 | A1               |
| V1.10            | 2012/8/30  | DCS-2210 | A1               |
| V1.20            | 2013/06/13 | DCS-2210 | A1               |

**Upgrading Instructions:**

1. Upgrading by using Web-UI

**New Features:**

| Fireware Version | New Features   |
|------------------|--|
| V1.00.00         | 1. New model MP FW release   |
| V1.10.02         | <ol style="list-style-type: none"><li>1. Add the manual trigger API.</li><li>2. Add IPv6, QoS, CoS, RTSP multicast, RTSP digest authentication</li><li>3. Enhance FTP to establish sub directory, Recoding size change to 50MB or 60 sec., Event video clip support up to 5MB.</li><li>4. Enhance DDNS account and password length to 63</li></ol> |
| V1.20.00         | <ol style="list-style-type: none"><li>1. Add SNMP function</li></ol>   |

**Problems Fixed:**

| Firmware Version | Problems Fixed  |
|------------------|---|
| V1.20.00         | <ol style="list-style-type: none"><li>1. Remove "guest" account.</li><li>2. RTSP authentication default enable</li><li>3. Fixed the security of UPNP.</li></ol> |

**Known Issues:**

| Firmware Version | Known Issues |
|------------------|--------------|
|                  | N/A          |

**Related Documentation:**

N/A