


## DGS-3100 series firmware and boot code update guide

**Caution: The PROM version 1.0.1.01 works with firmware version 2.50.43 and PROM version 1.0.1.04 works with firmware version 3.00.43. DO NOT PROCEED the upgrading without verifying the PROM and firmware combination first. Direct upgrade from incorrect PROM and firmware combination is not recommended. PLEASE DO NOT REBOOT THE SWITCH BEFORE YOU COMPLETE THE UPLOADING FOR BOTH PROM AND FIRMWARE.**

Warning: DGS-3100 series switch doesn't support update boot-code from Web GUI.


### **Topology:**



### **TFTP Server software needs to be running on computer:**

1. TFTP server IP address: 10.90.90.100.

TFTP server must be in the same folder as firmware and boot-code



**(P.S. In stacking mode, switch supports update firmware for all units at the same time but it doesn't support update boot code for all units at the same time)**